

M/S. N. ISLAM & CO

Tenderer's Quoted Price

Tenderer's Quoted Price

Total Estimated Cost (BDT)	Percentage (-5% to +5%)	Offered Amount (in figures) (BDT)	Offered Amount (in words) (BDT)
497490.000	-5.000	472615.500	Four Lakh Seventy-Two Thousand Six Hundred And Fifteen Point Five
	Grand Total:	472615.500	Four Lakh Seventy-Two Thousand Six Hundred And Fifteen Point Five

This Tenderer's Quoted Price is Electronically Signed by Mr. Md. Islam on behalf of M/S. N. ISLAM & CO

M/S. N. ISLAM & CO**Priced Bill of Quantities (BOQ)****Unit Rate Basis**

Estimate by the Procuring Entity

Item No.	Group	Item Code (If any)	Description of Items of Works (specifications preferably built-in)	Unit	Quantity	Unit rates or prices (in figures) (BDT)	Unit rates or prices (in words) (BDT)	Amount (in figure) (BDT)	Amount (in words) (BDT)	I have seen
1	N/A	Approved Rate	Servicing of split type Air conditioner, replacing the existing damaged stainer, dismantling the indoor & outdoor unit, maintenance of fan bearing, sensor, contact relay, copper tube & insulation system & reinstallation. Split type AC 5 Ton (60000 BTU/Hr)	No.	8.000	14725.000	Fourteen Thousand Seven Hundred And Twenty-Five	117800.000	One Lakh Seventeen Thousand Eight Hundred	I have seen
2	N/A	Approved Rate	Servicing of split type Air conditioner, replacing the existing damaged stainer, dismantling the indoor & outdoor unit, maintenance of fan bearing, sensor, contact relay, copper tube & insulation system & reinstallation. Split type AC 1.5/2 Ton (18000/24000 BTU/Hr)	No.	8.000	9816.000	Nine Thousand Eight Hundred And Sixteen	78528.000	Seventy-Eight Thousand Five Hundred And Twenty-Eight	I have seen
3	N/A	Approved Rate	After repair of leakage refrigerent 22/410/470 gas filling & replacing the compressor oil of split type Air conditioner. 4.5 Ton (54000 BTU/Hr)	No.	10.000	7300.000	Seven Thousand Three Hundred	73000.000	Seventy-Three Thousand	I have seen
4	N/A	Approved Rate	After repair of leakage refrigerent 22/410/470 gas filling & replacing the compressor oil of split type Air conditioner. 1.5/2 Ton (18000/24000 BTU/Hr)	No	10.000	3300.000	Three Thousand Three Hundred	33000.000	Thirty-Three Thousand	I have seen
5	N/A	Approved Rate	Replacement of damaged compressor by new compressor of 60000 BTU/Hr with	No.	3.000	65054.000	Sixty-Five Thousand And Fifty-Four	195162.000	One Lakh Ninety-Five Thousand One Hundred	I have seen

			over load all other safety control suitable for 415 v, 50 hz approved by engineer in charge						And Sixty- Two	
							Grand Total:	497490.000	Four Lakh Ninety- Seven Thousand Four Hundred And Ninety	

This Priced Bill of Quantities (BOQ) is Electronically Signed by Mr. Md. Islam on behalf of M/S. N. ISLAM & CO