

(19)

**Office of the Executive Engineer
MODS Zone-10, Dhaka WASA**

Cost Estimate

Subject : Repairing, maintenance and installation ork of CC camera system at MODS Zone-10 Office compound under MODS Zone-10, Dhaka WASA.

SL No	Rate Qutation	Description of the item	Unit	Quantity	Rate(Tk.)	Amount (Tk.)
1	Rate Qutation	Hikvision Full color Camera Model-1023G2LIU-A	pcs	16	4150.00	66400.00
2	"	Dahua Full Coper Cat-6 Cable	coil	2.00	12000.00	24000.00
3	"	POE Switch 8 port	pcs	2	6000.00	12000.00
4	"	POE Switch 4 port	pcs	6	4000.00	24000.00
5	"	Hard Disk 6TB	pcs	1	16000.00	16000.00
6	"	RJ 45 Connector	pcs	50	20.00	1000.00
7	"	BRB Power Cable	coil	2	4000.00	8000.00
8	"	Power Socket 6 Pin	pcs	4	500.00	2,000.00
9	"	Cable Wiring & Camera setup Charge	LS	LS	10000.00	10000.00
					Total =	163400.00

Total (In Word) : Tk One Lac Sixty Three Thousand Four Hundred only.

Rehana Begum
13.02.25
Rehana Begum
Sub-Assistant Engineer
MODS Zone-10
Dhaka WASA

Md. Barkatullah
13.02.25
Md. Barkatullah
Assistant Engineer
MODS Zone-10
Dhaka WASA

Sujon Chandra Barman
13/2/25
Sujon Chandra Barman
Executive Engineer
MODS Zone-10, Dhaka WASA