



**Office of the Executive Engineer
MODS Zone-10, Dhaka WASA**


Cost of Estimate : Heavy leakage repair and dirty water removal work in Uttara Sector-15/D & 15/H Area under Mods Zone-10, Dhaka WASA.

SL No	Rate Schedule	Description of the item	Unit	Quantity	Rate(Tk.)	Amount (Tk.)
1	pwd 02.10.1	Sand filling in foundation trenches and plinth with sand having minimum F.M. 0.5 to FM 0.8	cum	12.75	1118.00	14254.50
2	pwd 02.13	Back filling by excavated granular soil	cum	16.32	213.00	3476.16
3	pwd 02.14	Cleaning and disposing of excavated earth	cum	12.5	779.00	9737.50
4	Market rate fixed by WASA	Labour	P/Person	8	800.00	6400.00
5	Market rate fixed by WASA	Skilled technician/Mechanics for HDPE pipe cutting, fitting and operating cutting disk.	P/Person	2	1000.00	2000.00
6	Pre-Approved Rate	Hire Charge of electrofusion machine to joint sleeve in the excavation. all complete as per direction of the E/C.	P/day	1	1500.00	1500.00
7	WASA-20	Hire charge of de-watering Pump	P/Nos	3	1862.00	5586.00
8	Pre-Approved Rate	Generator Mechine Hire Charge	P/day	1	2,000.00	2,000.00
9	Market rate	Safety Barriers Bamboo, Wooden, Planked Rope, G.I Wire for temporary shoring and boxing to the side of the excavation to maintain a safe working environment for an depths.	LS	LS	3500.00	3500.00
					Total	48454.16

In Word : Forty Eight Thousand Four Hundred Fifty Four Point One Six Tk only.


মোজিব্বিন বিদ্যাহ অসমগীর
উপ-সহকারী প্রকৌশলী
মডস জোন-১০, ঢাকা ওয়াসা।


Manik Chandra Mohanayok
Assistant Engineer
MODS Zone-10
Dhaka WASA


Md. Abid Hossain
Executive Engineer
MODS Zone-10, Dhaka Wasa