

DHAKA WATER SUPPLY AND SEWERAGE AUTHORITY

98 Kazi Nazrul Islam Avenue, Kawran Bazar,
Dhaka-1215

Estimation Preparation Report

Estimation ID : EST25100013
Vehicle No : Dhaka Metro Ga-35-3987
Division : Transport Pool Section

Date : 28-OCT-25
Vehicle Type : CAR - SALOON

SL	Type of Maintenance	Spare Parts Name	Work Description	UOM	Quantity	Unit Price	Total Cost
1	SUSPENTION SYSTEM	Ball Joint (Lower)	The reason for the torn ball joint is that it needs to be replaced	SET	1	2850	2850
2	SUSPENTION SYSTEM	Stabilizer Bush (Front)	The reason for the torn stabilizer bush is that it needs to be replaced	SET	1	4500	4500
3	SUSPENTION SYSTEM	Shock Absorber (Front)	The shock absorber cylinder is leaking & needs to be replaced with a new one.	SET	1	14500	14500
4	SUSPENTION SYSTEM	Shock Absorber (Rear)	The shock absorber cylinder is leaking & needs to be replaced with a new one.	SET	1	12500	12500
5	BRAKE SYSTEM	Brake Pad (Front)	The brake pads have worn out due to long-term use, so new brake pad need to be added.	SET	1	8500	8500
6	BRAKE SYSTEM	Brake Shoe (Rear)	The brake shoes have worn out due to long-term use, so new brake shoes need to be added.	SET	1	7800	7800
7	BRAKE SYSTEM	Brake Oil	The brake oil level has decreased, so you need to add brake oil.	Pcs	2	500	1000
8	BRAKE SYSTEM	Brake Master Cylinder	The brake master cylinder is damaged & needs to be replaced with new one.	Pcs	1	12500	12500
9	SUSPENTION SYSTEM	Steering box Complete	Repaired -	Pcs	1	35000	35000
10	SUSPENTION SYSTEM	D Bush	The reason for the torn D bush is that it needs to be replaced	SET	1	3250	3250
11	Vehicle Dent & Paint	Front Cabin Dent & Paint with Polish	Inner outer polish & car wash	item	1	85000	85000

Total Cost 12 187400

VAT(10%) 0

Total Amount 187400

Amount in Words : One Lac Eighty Seven Thousand Four Hundred Only

MD. SULTAN MAHMUD : 5086

Transport Officer (CC)

Prepared By

Grand Total 187400

Amount in Words : One Lac Eighty Seven Thousand Four Hundred Only

মোঃ সুলতান মাহমুদ
পরিবহন কর্মকর্তা (চঃ দাঃ)
পরিবহন পুল
ঢাকা ওয়াশা
সদস্য সচিব
যানবাহন টেকনিক্যাল কমিটি

শেখ শফিকুল ইসলাম
সহকারী প্রকৌশলী
পিএভি (বাঃ ওভঃ) বিভাগ
সদস্য
পাকী মেমোরাল টেকনিক্যাল কমিটি
ঢাকা ওয়াশা, ঢাকা।

সাইদ শাহরিয়ার হোসাইনী
নির্বাহী প্রকৌশলী
পিএভি (বাঃ ওভঃ) বিভাগ
আইসিআর
যানবাহন টেকনিক্যাল কমিটি
ঢাকা ওয়াশা, ঢাকা।