



DHAKA WATER SUPPLY AND SEWERAGE AUTHORITY

98 Kazi Nazrul Islam Avenue, Kawran Bazar,
Dhaka-1215

Estimation Preparation Report

26	AC SYSTEM	Compressure Oil Seal	Compressor oil seal is torn & needs to be replaced.	SET	1	850	850
27	ENGINE AND GEAR PARTS	Oil Filter	New one is replaced	Pcs	1	1000	1000
28	ENGINE AND GEAR PARTS	Main bigend Bearing	The main bearings is worn out & needs to be replaced with a new one.	SET	1	6500	6500
29	SUSPENTION SYSTEM	Hanger bush Uper	The reason for the torn Hanger bush is that it needs to be replaced	Pcs	1	3200	3200
30	Service Charge	Machine Shop Bill		item	1	11000	11000
Total Cost					44		184949
VAT(10%)							0
Total Amount							184949

Amount in Words : One Lac Eighty Four Thousand Nine Hundred Forty Nine Only

MD. SULTAN MAHMUD : 5086

Transport Officer (CC)

Prepared By

Grand Total

184949

Amount in Words : One Lac Eighty Four Thousand Nine Hundred Forty Nine Only

মোঃ সুলতান মাহমুদ
পরিবহন কর্মকর্তা (চঃ দাঃ)
পরিবহন শুল্ক
ঢাকা ওয়াশা
সদস্য সচিব
যানবাহন টেকনিক্যাল কমিটি

শেখ শফিকুল ইসলাম
সহকারী প্রকৌশলী
পিএডভি (যাঃ ও তঃ) বিভাগ
সদস্য
গাড়ী মেরামত টেকনিক্যাল কমিটি
ঢাকা ওয়াশা, ঢাকা।

সাইদ শাহরিয়ার হোসাইনী
নির্বাহী প্রকৌশলী
পিএডভি (যাঃ ও তঃ) বিভাগ
আইসিআর
যানবাহন টেকনিক্যাল কমিটি
ঢাকা ওয়াশা, ঢাকা।