



ঢাকা পানি সরবরাহ ও পয়ঃ নিষ্কাশন কর্তৃপক্ষ

নির্বাহী প্রকৌশলীর কার্যালয়

দাশেরকান্দি পয়ঃশোধনাগার


আফতাবনগর, খিলগাঁও, ঢাকা-১২১৯।

পরীক্ষণ ও গ্রহণ কমিটির রিপোর্ট

কাজের নাম	৪ Supply of sludge incineration rotary kiln Induced draft fan & others equipment for SDIP of Dasherakandi STP.
কার্যাদেশ নং-	৪ ৪৬.১১৩.৬৩৭.০০.০০.২১৪.২০২৫-৫৩৯; তারিখঃ ২২/১১/২০২৬।
ঠিকাদারী প্রতিষ্ঠানের নাম	৪ M/S. Al Rashid Enterprise
ব্যবহারকারী বিভাগের নাম	৪ দাশেরকান্দি পয়ঃশোধনাগার।
সরবরাহের স্থান	৪ প্ল্যান্টের উপ-ভান্ডার।
সরবরাহের তারিখ	৪ ২৯/০৬/২০২৬ইং।
পরিদর্শনের তারিখ	৪ ৩০/০৬/২০২৬ইং

ক্রঃ নং	মালামালের বিবরণ	চুক্তি অনুযায়ী মালামাল ও কাজের পরিমাণ	একই কিস্তিতে প্রদেয় মালামাল ও সম্পাদিত কাজের পরিমাণ	একই কিস্তিতে গ্রহণযোগ্য মালামালের পরিমাণ	বাতিলকৃত মালামালের পরিমাণ
1.	Main induced draft fan Impeller Made in China. (As per existing sample/approved by the Engineer-in-charge).	1 Nos	1 Nos	1 Nos	নাই
2.	Main induced draft fan Shaft Made in China. (As per existing sample/approved by the Engineer-in-charge).	2 Nos	2 Nos	2 Nos	নাই
3.	Shaft bearing for Main induced draft fan Made in China. (As per existing sample/approved by the Engineer-in-charge).	4 Nos	4 Nos	4 Nos	নাই
4.	Coupling for Main induced draft fan Made in China. (As per existing sample/approved by the Engineer-in-charge).	2 Nos	2 Nos	2 Nos	নাই
5.	Vibration Absorber for Main induced draft fan Made in China. (As per existing sample/approved by the Engineer-in-charge).	38 Nos	38 Nos	38 Nos	নাই
6.	Seal for Main induced draft fan Made in China. (As per existing sample/approved by the Engineer-in-charge).	36 Nos	36 Nos	36 Nos	নাই
7.	Helical gearworm reducer with motor for SDIP Made in China. (As per existing sample/approved by the Engineer-in-charge).	2 Nos	2 Nos	2 Nos	নাই
8.	Rotary kiln blower for SDIP Made in China. (As per existing sample/approved by the Engineer-in-charge).	1 Nos	1 Nos	1 Nos	নাই

পরিদর্শন রিপোর্ট ও স্বাক্ষরঃ পরীক্ষণ ও গ্রহণ কমিটি কর্তৃক ৩০/০৬/২০২৬ তারিখে সরবরাহকৃত মালামাল পরিদর্শন করা হল। মালামালের পরিমাণ সঠিক আছে, Technical specification অনুযায়ী যথাযথ আছে এবং গুণগত মান সন্তোষজনক; বিধায় সমুদয় মালামাল পরীক্ষণ ও গ্রহণ কমিটি কর্তৃক গৃহীত হ'ল।


30/06/26

মোঃ আল আমিন
নির্বাহী প্রকৌশলী
দাশেরকান্দি পয়ঃশোধনাগার ও
সদস্য-সচিব, পরীক্ষণ ও গ্রহণ কমিটি
ঢাকা ওয়াসা।


30/06/26

মোঃ মোমতাজুর রহমান
নির্বাহী প্রকৌশলী
পিএন্ডডি (তড়িৎ ও যান্ত্রিক)
ও
সদস্য, পরীক্ষণ ও গ্রহণ কমিটি
ঢাকা ওয়াসা।


30/06/26

মির্জা গোলাম কিবরিয়া
তত্ত্বাবধায়ক প্রকৌশলী
পানি ও পয়ঃশোধনাগার সার্কেল ও
আহবায়ক, পরীক্ষণ ও গ্রহণ কমিটি
ঢাকা ওয়াসা।

Inspection Report

(Non-negotiable)

Inspector:	Kaifeng Zhang
Inspection location:	Wuxi City, Jiangsu Province, P.R. China
Date of inspection:	May. 06 & 13, 2026



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.
 This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.
 Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

B-4 Building, Ziyin (Baoba) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China
 Tel: +86(0)25-8345 9495 Fax: +86(0)25-8345 9107

IND

www.sgs.com.cn
sgs.china@sgs.com

Contents

- 1. Background information 3
- 2. Instrument 4
- 3. Quantity check (not including weight check) 4
- 4. Randomly Visual quality check 4
- 5. Randomly marking check 5
- 6. Randomly Packing check 6
- 7. Photo 6
- 8. Timesheet 13



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.
 This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.
 Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

IND

B-4 Building, Zijin (Baotai) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China
 Tel: +86(0)25-8346 8455 Fax: +86(0)25-8346 8107

www.sgs.com
sgs.china@sgs.com

1. Background information

SGS order No.:	NJINSCS2600237 Rev.01				
Coordinator:	Tang Qian		Telephone:	+86 (025) 8712 8307	
Description of commodity					
Item	Description of Goods	QTY (PO)	Actual QTY		
1	Main induced draft fan Impeller	1	1		
2	Main induced draft fan Shaft	2	2		
3	Shaft bearing for Main induced draft fan	4	4		
4	Coupling for Main induced draft fan	2	2		
5	Vibration Absorber for Main induced draft fan	40	40		
6	Seal for Main induced draft fan	36	48		
7	Helical gearworn reducer with motor for SDIP	2	2		
8	Rotary kiln blower for SDIP	2	2		
As per the product list provided by buyer					
Buyer					
M/S AL RASHID ENTERPRISE					
Seller					
Jiangsu Su Feng Ventilation Fan Co., Ltd.					
P/I No.	PI Code: SF20251215-001 (date 2025.12.15)				
Others	Product list provided by buyer				
Nature of inspection:	Item	Satisfactory	Non-conforming	Rejected	Subject to buyer's evaluation
	Quantity check (not including weight check)	●			
	Randomly Visual quality check				●
	Randomly marking check				●
	Randomly packing check	●			



SGS-CTI Standards Technical Services Co., Ltd.
Industrial Services

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.
This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.
Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

9-4 Building, Zijin (Baoda) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China
Tel: +86(0)25-8346 8455 Fax: +86(0)25-8346 8107

IND

www.sgs.com
sgs.china@sgs.com

2. Instrument

During the inspection, the following instrument calibration status has been checked for inspection:

No.	Name	ID No.	Measuring range	Calibrated ^[1] (Yes/No/NA)	Certificate NO.
1.	N/A				

[1] Calibrated

--- "Yes" means the instrument was calibrated and now is in the period of validity.

--- "No" means the instrument should be calibrated, in fact it was never calibrated or not calibrated before the expiry date.

--- "NA" means the instrument does not need to be calibrated in the view of its function.

3. Quantity check (not including weight check)

3.1 Reference documents:

- Goods Name and Quantity
- PIAL RASHID 15.12.2025

3.2 Inspection activity:

Inspector as per the Goods Name and Quantity list carried out the quantity check, the actual quantity not the same as the goods list, details see below table:

Item	Description of Goods	QTY (PO)	Actual QTY
1	Main induced draft fan Impeller	1	1
2	Main induced draft fan Shaft	2	2
3	Shaft bearing for Main induced draft fan	4	4
4	Coupling for Main induced draft fan	2	2
5	Vibration Absorber for Main induced draft fan	40	40
6	Seal for Main induced draft fan	36	48
7	Helical gearworm reducer with motor for SDIP	2	2
8	Rotary kiln blower for SDIP	2	2

Remark: The result was acceptable.

4. Randomly Visual quality check

4.1 Reference documents:

- Goods Name and Quantity



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.
This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.
Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

B-4 Building, Zijin (Babai) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China
Tel: +86(0)25-8346 9455 Fax: +86(0)25-8346 9107

IND

www.sgs.com.cn
e sgs.china@sgs.com

➤ PIAL RASHID 15.12.2025

4.2 Inspection activity:

When inspector arrived at the factory, most of the goods have been packaged, bearings have been installed on the shaft, and the motors also have been installed.

Randomly carried out the visual check, damage, deform and others defects for the most of the goods were not found, some defects were found on main induced draft fan impeller and Coupling for Main induced draft fan, the details see below:

The most weld seams looked smoothly, the but the spatters, pore and local poor weld seam were found on the main induced draft fan impeller.

The local paint damage was found on the Coupling for Main induced draft fan surface, and the paint inside the shaft hole has not been removed.

Details pls check the attached pictures.

Remark: The result was subject to buyer's evaluation.

5. Randomly marking check

5.1 Reference documents:

- Goods Name and Quantity
- PIAL RASHID 15.12.2025

5.2 Inspection activity:

As per the PO requirement carried out the marking check, details see below:

The marking for the main induced draft fan impeller, Main induced draft fan Shaft, Seal for Main induced draft fan and Coupling for Main induced draft fan were not found.

The bearings have been installed on the shafts, the marking and model were not found.

The certificate of conformity was stucked on the Vibration Absorber for Main induced draft fan surface, the type was JB-L, 1200kg, which the same as the Goods Name and Quantity list.

Helical gearworn reducer with motor for SDIP check, total 2sets, the nameplates for the motor and Helical gearworn reducer have been installed, the power was 2.2KW, and the voltage was 380V, the result was acceptable.

Rotary kiln blower for SDIP check, total 2sets, the nameplate and rotate direction marking have been installed on the equipment. Inspector carried out the motor nameplate contents check for the rotary kiln blower for SDIP, one of power (15KW) and voltage (400V) etc., contents the same as the PO. For another one, power (7.5KW) and voltage (400V), due to no relevant information provided before inspection, the result was subject to buyer's evaluation.



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.
This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.
Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

6-4 Building, Zijin (Baoda) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China.
Tel: +86(0)25-8346 8455 Fax: +86(0)25-8346 6107

IND

www.sgs.com
sgs.china@sgs.com

Remark: The result was subject to buyer's evaluation.

6. Randomly Packing check

6.1 Reference documents:

- Goods Name and Quantity
- PI AL RASHID 15.12.2025

6.2 Inspection activity:

As per requirement randomly carried out the packing check, most of the goods have been packaged, details see below:

The wooden box was made of plywood and its corners were reinforced with iron sheets.

The center, moisture-proof, forklift and other markings were found on the surface of the wooden box.


The Main induced draft fan Shaft, and Rotary kiln blower for SDIP have been packaged with plastic film.

The fasteners were placed in a paper box.


The helical gearworn reducer with motor for SDIP, fill the four sides with filling materials, and the quality certificate was also placed in the wooden box.

Remark: The result was acceptable.

7. Photo



1. Quantity check



2. Quantity check



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.
This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.
Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

B-4 Building, Zijin (Baotai) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China
Tel: +86(0)25-8346 8455 Fax: +86(0)25-8346 8107

IND

www.sgs.com
sgs.china@sgs.com



3. Quantity check




4. Quantity check



5. Quantity check



6. Quantity check



7. Visual check



8. Visual check



SGS China Standards Technical Service Co., Ltd.
Industrial Services

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.
This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.
Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

B-4 Building, Zijin (Baode) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China
Tel: +86(0)25-8346 9455 Fax: +86(0)25-8346 6107


IND

www.sgs.com
sgs.china@sgs.com


Member of the SGS Group (SGS SA)




9. Spatters were found



10. Poor weld seam was found




11. Pore was found



12. Paint damage was found



13. Paint was found at the shaft hole inside



14. Visual check



SGS China Inspection & Testing Services Co., Ltd.
Industrial Services

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.
This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.
Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

8-4 Building, Ziyin (Gaode) Technology Incubation Special Park, No.1 Guangshu Road, Nanjing, China
Tel: +86(0)25-8346 8455 Fax: +86(0)25-8346 8107

IND


www.sgs.com
sgs.china@sgs.com



15. Visual check




16. Visual check




17. Visual check



18. Visual check



19. Visual check



20. Visual check



SGS-CHINA Technical Services Co., Ltd.
Industrial Services

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.
This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.
Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

B-4 Building, Zijin (Beijin) Technology Incubation Special Park, No. 1 Guanghua Road, Nanjing, China
Tel: +86(0)25-8340 5495 Fax: +86(0)25-8340 9107


IND

www.sgs.com.cn
e: sgs.china@sgs.com

Member of the SGS Group (SGS SA)



21. Marking check



22. Marking check




23. Marking check



24. Marking check



25. Marking check



26. Marking check



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company. This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

B-4 Building, Zijin (Baidu) Technology Incubation Special Park, No.1 Guanghui Road, Nanjing, China
Tel: +86(0)25-8346 9455 Fax: +86(0)25-8346 8107


IND

www.sgs.com
sgs.china@sgs.com

Member of the SGS Group (SGS SA)




33. Packing check



34. Packing check




35. Packing check



36. Packing check



37. Packing check



38. Packing check



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

8-4 Building, Ziyin (Gaoxin) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China
Tel: +86(0)25-8346 9455 Fax: +86(0)25-8346 9107

IND

www.sgs.com
sgs.china@sgs.com

8. Timesheet

Name/Staff ID	Date	Working Hours	Overtime Hours
Zhang Kaifeng	May 6, 2025	8	
Zhang Kaifeng	May 13, 2025	8	
	/		
Total time charged		16	

Note: Both traveling time and reporting time are included.

THIS REPORT ONLY REFLECTED OUR ACTUAL FINDINGS. THE INSPECTION WAS DONE TO THE BEST OF OUR KNOWLEDGE AND ABILITY AND WITH DUE CARE. THE FINDINGS ARE VALID AS FOR TIME AND PLACE OF INSPECTION.

Issued by:	Kaifeng Zhang	Reviewed by:	Tang Qian.	Approved by:	Michael He
Title or position:	Inspector	Title or position:	Coordinator	Title or position:	Technical Manger
Date:	May 13, 2026	Date:	May 19, 2026	Date:	May 19, 2026

End of Report



SGS-CHINA Standards Technical Services Co., Ltd.
Industrial Services Technical

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.
This document is issued by the Company under its General Conditions of Service accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.
Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

8-4 Building, Zijin (Gaoxin) Technology Incubation Special Park, No.1 Guanghua Road, Nanjing, China
Tel: +86(0)25-8346 8455 Fax: +86(0)25-8346 8107

IND

www.sgs.com.cn
sgs.china@sgs.com