

**Office of the Executive Engineer
MODS Zone-9, Dhaka WASA
Estimate**

Name of work: Repair maintenance and Replace of broken glass of partition wall of new office building, Uttara Sector-6, under MODS Zone-9, Dhaka WASA.

SL No	Item Code	Description of the item	Unit	Quantity	Rate(Tk.)	Amount (Tk.)
I	PWD-14.16	Supplying, fitting and fixing in Aluminium door frames, windows, partitions and curtain wall distortion free glass of approved quality and shade including cost of fitting fixing all necessary accessories etc. complete in all respect as per drawing and accepted by the Engineer-in-charge.				
	14.16.3.2	8 mm thick clear tempered glass	Sqm	56.74	3853.001	218,619.28
	MR	Supplying of skilled Technician for safely remove of broken glass and disposal of further distant. Cleaning and washing working side. All completed as per direction by the Engineer.	Nos.	20.00	1000.001	20,000.02
18	26.70.2	Rouf, Bamboo, Cleaner etc lamp sum	Item	1	10,000.001	10,000.001
Total Amount of Tk=						248,619.298

In Word-Two Lac Forty Eight Thousand Six Hundred Ninetwene Point Two Nine Eight Taka Only.

Minir
27.08.24
মোঃ মনিরুজ্জামান
উপ-সহকারী প্রকৌশলী
মডস জোন-৯, ঢাকা ওয়াসা

Md. Nazmul Hussain
27.08.24
Md. Nazmul Hussain
Assistant Engineer
MODS Zone-9
Dhaka WASA

27.8.24
এস. এম. মাসুদ পারভেজ
নির্বাহী প্রকৌশলী
মডস জোন-৯, ঢাকা ওয়াসা

Name of the work: Repair maintenance of sanitary line with ancillary works of new office building, Uttara Sector-6, under MODS Zone-9, Dhaka WASA.

(A) CIVIL WORK

I	Color Wash		Length (ft.)	Breadth (ft.)	Height (ft.)	Number	F.P.S		M.K.S.	
	a	Soth side wall	4.50		3.50	34	535.50			
	b	Parttion Wall	20.00		2.00	1	40.00			
	c		10.00		3.50	1	35.00			
	Sub Total						610.50	Sft	56.74	Sqm
2	a	Skilled Technician							20	Nos.

Munir
27.08.24
মোঃ মনিরুজ্জামান
উপ-সহকারী প্রকৌশলী
মডস জোন-৯, ঢাকা ওয়াসা

Md. Nazmul Hussain
27.08.24
Md. Nazmul Hussain
Assistant Engineer
MODS Zone-9
Dhaka WASA

As. M. Masud Parbes
27.08.24
এস. এম. মাসুদ পারভেজ
নির্বাহী প্রকৌশলী
মডস জোন-৯, ঢাকা ওয়াসা