

Accessory Report

Start Date

End Date

Complain Type	Accessory Name	Fm Division	Mods Zone	Pump House	Pump Info	Duty Officer Name
Sub Pump cable burnt	Ferul	FM Division-2	Mods Zone-5	Banani - Old DOHS	Banani - Old DOHS - 2	Md Abul Hossain
Sub Pump cable burnt	Plaistic Tape	FM Division-2	Mods Zone-5	Banani - Old DOHS	Banani - Old DOHS - 2	Md Abul Hossain
cable fault	Ferul 50mm	FM Division-2	Mods Zone-5	Banani - Old DOHS	Banani - Old DOHS - 2	Md Abul Hossain
cut out burning	150 A Cut out	FM Division-2	Mods Zone-5	BG Press staff quarter	BG Press staff quarter (12/03/21)	Md Abul Hossain
cable fault	Ferul 50mm	FM Division-2	Mods Zone-5	BG Press staff quarter	BG Press staff quarter (12/03/21)	Md Abul Hossain
vfd problem	Link fuse	FM Division-2	Mods Zone-5	Tejgaon Thana Compound	Tejgaon Thana Compound	Riad Ahmed
Circuit breaker problem	Circuit Breaker 250A	FM Division-2	Mods Zone-5	Banani-4	Banani-4	Riad Ahmed
cable fault	Cable socket 70	FM Division-2	Mods Zone-8	Badda Naya Nagar	Badda Naya Nagar(01/02/15)	Md Anisul Haque
Low production	0.75 cusec 125 m head pump-motor set	FM Division-2	Mods Zone-5	Banani-6	Banani-6 (04/07/17)	Md Abul Hossain
Low production	Nat Bolt	FM Division-2	Mods Zone-5	Banani-6	Banani-6 (04/07/17)	Md Abul Hossain
Low production	Ferul	FM Division-2	Mods Zone-5	Banani-6	Banani-6 (04/07/17)	Md Abul Hossain
Low production	Plaistic Tape	FM Division-2	Mods Zone-5	Banani-6	Banani-6 (04/07/17)	Md Abul Hossain
Low production	PIV Tape	FM Division-2	Mods Zone-5	Banani-6	Banani-6 (04/07/17)	Md Abul Hossain
Low production	5/8" Washer	FM Division-2	Mods Zone-5	Banani-6	Banani-6 (04/07/17)	Md Abul Hossain
vfd problem	1.0 cusec 125m head Sub_pump	FM Division-2	Mods Zone-5	Tejgaon Thana Compound	Tejgaon Thana Compound(21/10/20)	Md Abul Hossain
vfd problem	Plastic tape	FM Division-2	Mods Zone-5	Tejgaon Thana Compound	Tejgaon Thana Compound(21/10/20)	Md Abul Hossain
vfd problem	Nutbolt 5/8"	FM Division-2	Mods Zone-5	Tejgaon Thana Compound	Tejgaon Thana Compound(21/10/20)	Md Abul Hossain
vfd problem	MS waser 5/8"	FM Division-2	Mods Zone-5	Tejgaon Thana Compound	Tejgaon Thana Compound(21/10/20)	Md Abul Hossain
vfd problem	Ferul 70mm	FM Division-2	Mods Zone-5	Tejgaon Thana Compound	Tejgaon Thana Compound(21/10/20)	Md Abul Hossain

Complain Type	Accessory Name	Fm Division	Mods Zone	Pump House	Pump Info	Duty Officer Name
Low production	0.5 cusec 110m head Sub_pump	FM Division-2	Mods Zone-5	BG Press Math	BG Press Math	Md. Symul Haque
Low production	Column pipe 6"	FM Division-2	Mods Zone-5	Gulshan-4	Gulshan-4 (16/10/15)	Md Abul Hossain
HT fuse blown	Dofc	FM Division-2	Mods Zone-5	Mohakhali DOHS -1	Mohakhali DOHS -1	Md Abul Hossain
HT fuse blown	Link Fuse	FM Division-2	Mods Zone-5	Mohakhali DOHS -1	Mohakhali DOHS -1	Md Abul Hossain
Low production	6" column pipe	FM Division-2	Mods Zone-5	Mohakhali DOHS -1	Mohakhali DOHS -1	Md Abul Hossain
Low production	3x25 mm	FM Division-2	Mods Zone-5	Mohakhali DOHS -1	Mohakhali DOHS -1	Md Abul Hossain
Low production	Ferul	FM Division-2	Mods Zone-5	Mohakhali DOHS -1	Mohakhali DOHS -1	Md Abul Hossain
Low production	Plaistic Tape	FM Division-2	Mods Zone-5	Mohakhali DOHS -1	Mohakhali DOHS -1	Md Abul Hossain
Low production	cable socket	FM Division-2	Mods Zone-5	Mohakhali DOHS -1	Mohakhali DOHS -1	Md Abul Hossain
vfd problem	Link fuse	FM Division-2	Mods Zone-5	Mohakhali DOHS -1	Mohakhali DOHS -1	Riad Ahmed
cut out burning	150 A Cut out	FM Division-2	Mods Zone-5	Kawran Bazar	Kawran Bazar	Md Abul Hossain
cable fault	0.5 cusec 110m head Sub_pump	FM Division-2	Mods Zone-5	Kawran Bazar	Kawran Bazar	Md Abul Hossain
HT fuse blown	Link fuse	FM Division-2	Mods Zone-5	Banani -7	Banani -7 (23/01/20)	Riad Ahmed
HT fuse blown	3x16 mm	FM Division-2	Mods Zone-5	Tejgaon Sewer Lift Station	Tejgaon Sewer Lift Station	Md Abul Hossain
HT fuse blown	Plaistic Tape	FM Division-2	Mods Zone-5	Tejgaon Sewer Lift Station	Tejgaon Sewer Lift Station	Md Abul Hossain
HT fuse blown	PIV Tape	FM Division-2	Mods Zone-5	Tejgaon Sewer Lift Station	Tejgaon Sewer Lift Station	Md Abul Hossain
HT fuse blown	Link Fuse	FM Division-2	Mods Zone-5	Tejgaon Sewer Lift Station	Tejgaon Sewer Lift Station	Md Abul Hossain
HT fuse blown	Drop out isolator	FM Division-2	Mods Zone-5	Tejgaon Sewer Lift Station	Tejgaon Sewer Lift Station	Md Abul Hossain
cable fault	Ferul 50mm	FM Division-2	Mods Zone-5	Tejgaon Sewer Lift Station	Tejgaon Sewer Lift Station	Md Abul Hossain
Circuit breaker problem	Circuit Breaker 200A	FM Division-2	Mods Zone-5	Mohakhali, Health Complex	Mohakhali, Health Complex	Md Abul Hossain
Circuit breaker problem	Circuit Breaker 200A	FM Division-2	Mods Zone-5	Mohakhali, Health Complex	Mohakhali, Health Complex	Md Abul Hossain

Complain Type	Accessory Name	Fm Division	Mods Zone	Pump House	Pump Info	Duty Officer Name
cable fault	Ferul 50mm	FM Division-2	Mods Zone-5	Gulshan Wonderland	Gulshan Wonderland	Riad Ahmed
Pump Breakdown	1.5 cusec 125 (m) Head	FM Division-2	Mods Zone-5	Mohakali Cha Block	Mohakali Cha Block (02/05/21)	Md Abul Hossain
Pump Breakdown	Gasket	FM Division-2	Mods Zone-5	Mohakali Cha Block	Mohakali Cha Block (02/05/21)	Md Abul Hossain
Pump Breakdown	Nat Bolt	FM Division-2	Mods Zone-5	Mohakali Cha Block	Mohakali Cha Block (02/05/21)	Md Abul Hossain
Pump Breakdown	cable socket	FM Division-2	Mods Zone-5	Mohakali Cha Block	Mohakali Cha Block (02/05/21)	Md Abul Hossain
Pump Breakdown	Ferul	FM Division-2	Mods Zone-5	Mohakali Cha Block	Mohakali Cha Block (02/05/21)	Md Abul Hossain
Pump Breakdown	Plaistic Tape	FM Division-2	Mods Zone-5	Mohakali Cha Block	Mohakali Cha Block (02/05/21)	Md Abul Hossain
Pump Breakdown	PIV Tape	FM Division-2	Mods Zone-5	Mohakali Cha Block	Mohakali Cha Block (02/05/21)	Md Abul Hossain
Pump Breakdown	5/8" Washer	FM Division-2	Mods Zone-5	Mohakali Cha Block	Mohakali Cha Block (02/05/21)	Md Abul Hossain
Pump Breakdown	6" column pipe	FM Division-2	Mods Zone-5	Mohakali Cha Block	Mohakali Cha Block (02/05/21)	Md Abul Hossain
Pump Breakdown	3x35 mm	FM Division-2	Mods Zone-5	Mohakali Cha Block	Mohakali Cha Block (02/05/21)	Md Abul Hossain
Circuit breaker problem	Circuit Breaker 200A	FM Division-2	Mods Zone-5	Mohakhali T&T	Mohakhali T&T (08/11/015)	Md Abul Hossain
voltage up down	VFD 90kw	FM Division-2	Mods Zone-8	Joar Sahara-3, Olipara	Joar Sahara-3, Olipara	Md. Mahabubul Haque Pramanik
Fuse Disconnecter Switch problem	Link fuse	FM Division-2	Mods Zone-8	Joar Sahara-1	Joar Sahara-1	Md Anisul Haque
Low production	Plaistic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	Ferul	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	Nat Bolt	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	PIV Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Motor Burning	Plaistic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Motor Burning	PIV Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Motor Burning	Nat Bolt	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain

Complain Type	Accessory Name	Fm Division	Mods Zone	Pump House	Pump Info	Duty Officer Name
Motor Burning	Gasket	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	Plaistic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	Nat Bolt	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	Gasket	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	PIV Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	Ferul	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	Plaistic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	Nat Bolt	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	PIV Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Pump Cable Burning	Plaistic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Pump Cable Burning	Gasket	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Pump Cable Burning	Ferul	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Pump Cable Burning	PIV Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	Plaistic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	Gasket	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	Nat Bolt	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	PIV Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Motor Burning	Plaistic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Motor Burning	Ferul	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Motor Burning	PIV Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Motor Burning	Nat Bolt	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Motor Burning	Gasket	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain

Complain Type	Accessory Name	Fm Division	Mods Zone	Pump House	Pump Info	Duty Officer Name
Low production	Plaistic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	PIV Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Low production	Nat Bolt	FM Division-2	Mods Zone-4	Ahmed Nagar-2	Ahmed Nagar-2 (20/04/12)	Md Abul Hossain
Motor Burning	Plastic Tape	FM Division-2	Mods Zone-4	Duaripara Anobic Shokti	Duaripara Anobic Shokti (06/06/2016)	Md Abul Hossain
Motor Burning	PIV Tape	FM Division-2	Mods Zone-4	Duaripara Anobic Shokti	Duaripara Anobic Shokti (06/06/2016)	Md Abul Hossain
Motor Burning	Ferul	FM Division-2	Mods Zone-4	Duaripara Anobic Shokti	Duaripara Anobic Shokti (06/06/2016)	Md Abul Hossain
Motor Burning	Nat Bolt	FM Division-2	Mods Zone-4	Duaripara Anobic Shokti	Duaripara Anobic Shokti (06/06/2016)	Md Abul Hossain
Low production	Plastic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Low production	PIV Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Low production	Nat Bolt	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Motor Burning	Plaistic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Motor Burning	Nat Bolt	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Motor Burning	PIV Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Motor Burning	Gasket	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
gasket leakage	Plaistic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
gasket leakage	Gasket	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
gasket leakage	Nat Bolt	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Motor Burning	Plaistic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Motor Burning	PIV Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Motor Burning	Nat Bolt	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Motor Burning	Gasket	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Motor Burning	Plaistic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain

Complain Type	Accessory Name	Fm Division	Mods Zone	Pump House	Pump Info	Duty Officer Name
Motor Burning	PIV Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Motor Burning	Nat Bolt	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Motor Burning	Gasket	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Low production	Plaistic Tape	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Low production	Nat Bolt	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Low production	Ferrule	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Pump Cable Burning	Plastic tape	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Pump Cable Burning	Ferul 50mm	FM Division-2	Mods Zone-4	Ahmed Nagar-1	Ahmed Nagar-1 (28/08/17)	Md Abul Hossain
Partial Damage of Pump	1.0 cusec 110m head Sub_pump	FM Division-2	Mods Zone-8	Baridhara DOHS-1	Baridhara DOHS-1 ((07/03/15)	Foysal Khan
High vibration in pump	0.75 cusec 125m head Sub_pump	FM Division-2	Mods Zone-5	Banani-9	Banani-9	Md Abul Hossain
HT fuse blown	DOFC	FM Division-2	Mods Zone-5	Banani Jamai Bazar (1st Well 2016)	Banani jamai Bazar	Riad Ahmed
HT fuse blown	Link fuse	FM Division-2	Mods Zone-5	Banani Jamai Bazar (1st Well 2016)	Banani jamai Bazar	Riad Ahmed
Motor Burning	1.5 cusec 110m head Sub_pump	FM Division-2	Mods Zone-4	Agargoan-1	Agargoan- (02/09/21)	Md Abul Hossain
Motor Burning	Plastic tape	FM Division-2	Mods Zone-4	Agargoan-1	Agargoan- (02/09/21)	Md Abul Hossain
Motor Burning	Pib tape	FM Division-2	Mods Zone-4	Agargoan-1	Agargoan- (02/09/21)	Md Abul Hossain
Motor Burning	Rubber Gaskit 6"	FM Division-2	Mods Zone-4	Agargoan-1	Agargoan- (02/09/21)	Md Abul Hossain
Motor Burning	Ferul 50mm	FM Division-2	Mods Zone-4	Agargoan-1	Agargoan- (02/09/21)	Md Abul Hossain
Motor Burning	Nutbolt 5/8"	FM Division-2	Mods Zone-4	Agargoan-1	Agargoan- (02/09/21)	Md Abul Hossain
Low production	1.5 cusec 125m head Sub_pump	FM Division-2	Mods Zone-4	Agargoan-1	Agargoan- (02/09/21)	Md Abul Hossain
Low production	Plastic tape	FM Division-2	Mods Zone-4	Agargoan-1	Agargoan- (02/09/21)	Md Abul Hossain
Low production	Pib tape	FM Division-2	Mods Zone-4	Agargoan-1	Agargoan- (02/09/21)	Md Abul Hossain

Complain Type	Accessory Name	Fm Division	Mods Zone	Pump House	Pump Info	Duty Officer Name
Low production	Nutbolt 5/8"	FM Division-2	Mods Zone-4	Agargoan-1	Agargoan- (02/09/21)	Md Abul Hossain
Low production	Rubber Gaskit 6"	FM Division-2	Mods Zone-4	Agargoan-1	Agargoan- (02/09/21)	Md Abul Hossain
Low production	Ferul 50mm	FM Division-2	Mods Zone-4	Agargoan-1	Agargoan- (02/09/21)	Md Abul Hossain