

Ref: IT-Bill-WASA-19042026-01

To,
Senior System Analyst
MIS & Billing Department
WASA Bhaban, Kawran Bazar,
Dhaka WASA. Dhaka-1216.

April 19, 2026

Paia
29.04.26

Sub: Bill for Service Machines for Pump Houses in Dakkhin Rajarbag, Dakkhin Komlapur, Beauty Boding, Mirpur 6/A-B Pump, Shewrapara-02, Mirpur Section 6/K.

Dear Sir,
Regarding the previously mentioned subject, I am pleased to inform you that we have successfully Repair, Maintenance with Spare Parts and installed the mentioned pump houses in accordance with your specifications. Kindly proceed with the settlement of the invoice.

BILL

S/L	PRODUCE/ SPARES DESCRIPTION	Device Location/ Pump Houses	Zone / Offices	QTY.	UNIT PRICE	TOTAL PRICE
1.	1. Adaptor-1 Pc 2. Base-1 Pc	Dakkhin Rajarbag	MODS Zone-1	01 Set	2,830.00	2,830.00
2.	1. Finger Cabel-1 2. Adapter-1 3. Base-1	Dakkhin Komlapur	MODS Zone-1	01 Set	4,006.00	4,006.00
3.	1. Finger Sensor-1 2. Finger Cabel-1 3. Adapter-1 4. Base-1	Beauty Boding	MODS Zone-1	01 Set	9,506.00	9,506.00
4.	1. Base-1 Pc	Mirpur 6/A-B Pump	MODS Zone-4	01 Set	1,764.00	1,764.00
5.	1. Base-1 Pc	Shewrapara-02	MODS Zone-4	01 Set	1,764.00	1,764.00
6.	1. Base-1 Pc	Mirpur Section 6/K (Opposite of MIRPUR Stadium)	MODS Zone-4	01 Set	1,764.00	1,764.00
Total Amount:						21,624.00
In Word: Twenty-One Thousand Six Hundred and Thirty-Four Taka Only.						

Terms and Conditions

- Intelligent Technology** will provide (01) one-month service warranty for device; however, no warranty is provided for attendance device & any others spare parts if,
 - Warranty doesn't acceptable against natural disaster, burn case for AC INPUT power fluctuation or any mechanical/Physical damage.

Alex



- Warranty doesn't acceptable of the product if "warranty void seal" removed or tempered.
- 2. The Device and its accessories cannot be exchanged or replaced once used.
- 3. The payment for the services will be made through cash/an account payee cheque/DD/pay order, payable to **Intelligent Technology**, along with a corresponding work order.
- 4. This bill must be paid by Bangladesh Taka Only.

Please take necessary step to clear the bill to the following accounts details.

Account Name: Intelligent Technology

Bank Name: Bank Asia Ltd.

Branch: Satmosjid Road

Account Number: 06933000526

Account Type: Current

Receiving Bank Routing Number: 070264034

Mobile: 01904400201

Thank you for your prompt attention to this matter. We assure you that we provide our best service at all times.

Thank you once again.

Yours Sincerely,



Engr. Shamsul Alam

Manager (Technical)

For, **Intelligent Technology**

Cell: +88 01904400202, +88 01904400203.

E-mail: alam.itechbd@gmail.com

info.itechbd@yahoo.com

Web: www.itechbd.com



SERVICE / MAINTENANCE REPORT

For Biometric (Fingerprint / Face Detection) Time Attendance System

Maintenance Card No : IT-DW-MSA- Service Date : 12.04.2026

Client Name & Location : DHAKA WASA, 98, Kazi Nazrul Islam Avenue, Kawran Bazar, Dhaka-1215.

Office / Zone / Site Name : MODS ZONE - 01

Office / Zone / Site Location : Dakkhin Rajanbag

Application System : Biometric (Fingerprint / Face Detection) Time Attendance System.

Reported Fault By The Client :	The device was automatic restart problem.	
Action Taken By The Engineer/ Technician Comments:	Now the device service complete and the device was connected.	
Materials Used:	i) Base — 1 pcs. ii) Adapter — 1 pcs.	
Engineer / Technician Name : Biplob Kumar Roy .		
Engineer / Technician Signature : Biplob		Date : 12.04.2026
Client Representative's Name : Md. Saiful Islam		
Client Representative's Designation : P.O.		
Client Representative's Signature : Saiful		
Client Representative's Seal:		Date: 12.04.2026
Note:		

Signature
12/4/26

SERVICE / MAINTENANCE REPORT

For Biometric (Fingerprint / Face Detection) Time Attendance System

Maintenance Card No : IT-DW-MSA- Service Date : 12.04.2026

Client Name & Location : DHAKA WASA, 98, Kazi Nazrul Islam Avenue, Kawran Bazar, Dhaka-1215.

Office / Zone / Site Name : MODS ZONE-01

Office / Zone / Site Location : DOKKHIN Komlapur.

Application System : Biometric (Fingerprint / Face Detection) Time Attendance System.

Reported Fault By The Client :	The device was automatic resistant problem.	
Action Taken By The Engineer/ Technician Comments:	Now the device service complete and the device was connected.	
Materials Used:	i) Base — 1 PCS. ii) Adapter — 1 PCS.	
Engineer / Technician Name : Biplob kumar Roy		
Engineer / Technician Signature : Biplob		Date : 12.04.2026
Client Representative's Name : Amjed		
Client Representative's Designation : A.B.O.		
Client Representative's Signature : Amjed		Date : 12.04.2026
Client Representative's Seal:		
Note:		

Amjed
12/4/26

SERVICE / MAINTENANCE REPORT

For Biometric (Fingerprint / Face Detection) Time Attendance System

Maintenance Card No : IT-DW-MSA- Service Date : 12.04.2026

Client Name & Location : DHAKA WASA, 98, Kazi Nazrul Islam Avenue, Kawran Bazar, Dhaka-1215.

Office / Zone / Site Name : MODS ZONE - 01

Office / Zone / Site Location : Beauty Boding.

Application System : Biometric (Fingerprint / Face Detection) Time Attendance System.

Reported Fault By The Client :	The device was automatic restart problem.	
Action Taken By The Engineer/ Technician Comments:	Now the device service complete and the device was connected.	
Materials Used:	i) Base - 1 pcs. ii) Adapter - 1 pcs.	
Engineer / Technician Name :	Biplob kumar Roy.	
Engineer / Technician Signature :	Biplob	Date : 12.04.2026
Client Representative's Name :	স্বদেশী সান্না	
Client Representative's Designation :	P.O (O.S)	
Client Representative's Signature :	স্বদেশী	
Client Representative's Seal:		Date: 12.04.2026
Note:		

12/4/26

SERVICE / MAINTENANCE REPORT

For Biometric (Fingerprint / Face Detection) Time Attendance System

Maintenance Card No : IT-DW-MSA- Service Date : 07.04.26

Client Name & Location : DHAKA WASA, 98, Kazi Nazrul Islam Avenue, Kawran Bazar, Dhaka-1215.

Office / Zone / Site Name : MODS ZONE - 04

Office / Zone / Site Location : Minpur 6 AB Water pump.

Application System : Biometric (Fingerprint / Face Detection) Time Attendance System.

Reported Fault By The Client :	The device was automatic restart problem.	
Action Taken By The Engineer/ Technician Comments:	Now the device service complete and the device was connected.	
Materials Used:	i) Base - 1 pcs. ii) Adapter - 1 pcs.	
Engineer / Technician Name :	Biplob Kumar Roy	
Engineer / Technician Signature :	Junior Engineer.	Date : 07.04.26
Client Representative's Name :		
Client Representative's Designation :		
Client Representative's Signature :		
Client Representative's Seal:		Date: 07.04.26
Note:		

Mashur

মোঃ জাশিউর রহমান
উপ-সহকারী প্রকৌশলী
মডস জোন-৪, ঢাকা ওয়াসা।

SERVICE / MAINTENANCE REPORT

For Biometric (Fingerprint / Face Detection) Time Attendance System

Maintenance Card No : IT-DW-MSA- Service Date : 07.04.2026
Client Name & Location : DHAKA WASA, 98, Kazi Nazrul Islam Avenue, Kawran Bazar, Dhaka-1215.
Office / Zone / Site Name : MODS ZONE - 04
Office / Zone / Site Location : Shawrapara - 2 water pump
Application System : Biometric (Fingerprint / Face Detection) Time Attendance System.

Reported Fault By The Client :	The device was automatic restart problem .
Action Taken By The Engineer/ Technician Comments:	Now the device service complete and the device was connected.
Materials Used:	i) Base - 1 pcs. ii) Adapter - 1 pcs.
Engineer / Technician Name : Biplob Kumar Roy	
Engineer / Technician Signature : Junour Engineer	Date : 07.04.26
Client Representative's Name : Forhad Ahmed	
Client Representative's Designation : AP O	
Client Representative's Signature : 	
Client Representative's Seal:	Date: 07.04.26
Note:	

SERVICE / MAINTENANCE REPORT

For Biometric (Fingerprint / Face Detection) Time Attendance System

Maintenance Card No : IT-DW-MSA- Service Date : 07.04.26

Client Name & Location : DHAKA WASA, 98, Kazi Nazrul Islam Avenue, Kawran Bazar, Dhaka-1215.

Office / Zone / Site Name : MODS ZONE - 04 .

Office / Zone / Site Location : Mirpur - 06 / K water pump

Application System : Biometric (Fingerprint / Face Detection) Time Attendance System.

Reported Fault By The Client :	The device was automatic resistant problem .	
Action Taken By The Engineer/ Technician Comments:	Now the device service complete and the device was connected .	
Materials Used:	i) Base - 1 pcs. ii) Adapter - 1 pcs .	
Engineer / Technician Name : Triptob kumar Roy		
Engineer / Technician Signature : Junour Engineer .		Date : 07.04.26
Client Representative's Name : Md. Jahangir Alam Sarkar .		
Client Representative's Designation : A.P.O .		
Client Representative's Signature : 		
Client Representative's Seal:		Date : 07.04.26
Note:		