


Office of the Executive Engineer
MODS Zone-10, Dhaka WASA
Inspection & Work Completion Report

1. Name of the work : 315 mm Sluice Valve Chamber repair work in front of Madanash Road Pump, area of DMA 1006 Under MODS Zone-10, Dhaka WASA.
2. Name of the Contractor : M/S. F B Enterprise.
3. Estimated Amount : Tk-46,234/-
4. Contract Value : Tk-46,234/-
5. Bill Amount : Tk-46,234/- (Forty Six Thousand Two Hundred Thirty Four) Tk. Only.
6. Work order no & Date : 46.113.415.00.00.13.2026-06/2026-27; Date: 03/08/2026
7. Working Period (As per Work Order) : 5 Days
8. Actual Starting Date : 03/08/2026
9. Date of Completion : 07/08/2026
10. Completion Period : Within the Work Order
11. Description of executed works : As per BoQ (Bill of Quantities)

(The said work was started as per the specified time of the work order and completed within the stipulated time as per the specification as per the instructions of the engineer in charge.)


07.08.26
Sub-Assistant Engineer
MODS Zone-10, Dhaka WASA


09/08/26
Assistant Engineer
MODS Zone-10, Dhaka WASA


09/08/26
Executive Engineer
MODS Zone-10, Dhaka WASA


09/08/26
Superintending Engineer