

Office of the Executive Engineer  
MODS Zone-10, Dhaka WASA

**Inspection & Work Completion Report**

- 1 Name of the work : Leakage Repair work on Various road in Holly Apartment area DMA-1002 under MODS Zone-4, Dhaka WASA
- 2 Name of the Contractor : Nehan Enterprise
- 3 Estimated Amount : Tk-47,995.15/-
- 4 Contract Value : Tk-47,995.15/-
- 5 Bill Amount : Tk-47,995.15/- (Forty Seven Thousand Nine Hundred Ninety-Five Point One Five) Tk. Only.
- 6 Work order no & Date : 46.113.408.00.00.23.2026-15  
Date: 11/08/2026
- 7 Working Period (As per Work Order) : 3 Days
- 8 Actual Starting Date : 11/08/2026
- 9 Date of Completion : 13/08/2026
- 10 Completion Period : Within the Work Order
- 11 Description of executed works : As per BOQ (Bill of Quantities)

(The said work was started as per the specified time of the work order and completed within the stipulated time as per the specification as per the instructions of the engineer in charge.)

  
Sub-Assistant Engineer  
MODS Zone-10, Dhaka WASA

  
Assistant Engineer  
MODS Zone-10, Dhaka WASA

  
Executive Engineer  
MODS Zone-10, Dhaka WASA

  
Superintending Engineer  
MODS Circl-2, Dhaka WASA