




Work Completion Report

1. Name of the work : Repair of damaged manhole and removal of sewage overflow at 105 Lalbagh under PSTP Division.
- Office address : Pagla Sewage Treatment Plant Division
Dhaka WASA, Kadomtoli, Dhaka-1204.
2. Particulars of the Contactor/Firm
a) Name : M/S. TUBA Construction.
b) Address : 39/3, Manik Bagar, Mugda, Dhaka-1203
3. Description of work
a) Name of work : Repair of damaged manhole and removal of sewage overflow at 105 Lalbagh under PSTP Division.
b) Situation of Work : Executive Engineer office.
4. Full Particulars of the Department /Division : PSTP Division,
Dhaka WASA, Dhaka.
Which the work has been executed
5. Contract value of the work : Tk. **49,509.570** (Forty Nine Thousand **Five** Hundred **Nine** Point Five **Seven**)
6. Memo No & Date of Work Order : Work Order No. 46.113.433.00.00.2025-26.143-201
Date: 18-Jan-2026
7. Date of Commencement of work : 18/01/2026
8. Date of Completion : 30/01/2026
9. Work completion period : 12 (Twelve) days.
10. Description of executed works : The work has been executed as per specification and as per instruction of the engineer-in-charge.


Md. Mamunur Rahaman
Sub-Assistant Engineer
PSTP Division, DWASA


16.6.2026
Md. Saiful Islam
Sub-Divisional Engineer
PSTP Division, DWASA


Syed Shihabur Rahman
Executive Engineer
PSTP Division, DWASA