



ঢাকা পানি সরবরাহ ও পয়ঃ নিষ্কাশন কর্তৃপক্ষ

নির্বাহী প্রকৌশলীর কার্যালয়

দাশেরকান্দি পয়ঃশোধনাগার


আফতাবনগর, খিলগাঁও, ঢাকা-১২১৯।

পরীক্ষণ ও গ্রহণ কমিটির রিপোর্ট

কাজের নাম	ঃ Procurement of necessary Spare Parts such as Piston, were plate, S type switch valve, Transfer valve front end bearing seat, 140 main Cylinder, Water pool radiator, main pump, Chain & bucket etc. for Plunger Pump and SDIP of Dasherbandi STP, Dhaka WASA.
চুক্তি নং-	ঃ ৪৬.১১৩.৬৩৭.০০.০০.০৮৩.২০২৪-৬০১; তারিখঃ ০৪/১২/২০২৫।
ঠিকাদারী প্রতিষ্ঠানের নাম	ঃ M/S. Ayesha Enterprise
ব্যবহারকারী বিভাগের নাম	ঃ দাশেরকান্দি পয়ঃশোধনাগার।
সরবরাহের স্থান	ঃ প্ল্যান্টের উপ-ভান্ডার।
সরবরাহের তারিখ	ঃ ২১/০৬/২০২৬ইং।
পরিদর্শনের তারিখ	ঃ ২৩/০৬/২০২৬ইং

ক্রঃ নং	মালামালের বিবরণ	চুক্তি অনুযায়ী মালামাল ও কাজের পরিমাণ	একই কিস্তিতে প্রদেয় মালামাল ও সম্পাদিত কাজের পরিমাণ	একই কিস্তিতে গ্রহণযোগ্য মালামালের পরিমাণ	বাতিলকৃত মালামালের পরিমাণ
1.	S type switch valve; GYP40; Origin: China	2 Nos	2 Nos	2 Nos	নাই
2.	Transfer valve front end bearing seat GYP40; Origin: China	2 Nos	2 Nos	2 Nos	নাই
3.	Piston; GYP40; Origin: China	2 Nos	2 Nos	2 Nos	নাই
4.	wear plate; GYP40; Origin: China	2 Nos	2 Nos	2 Nos	নাই
5.	wear ring; GYP40; Origin: China	2 Nos	2 Nos	2 Nos	নাই
6.	Transfer valve front rear bearing seat GYP40; Origin: China	2 Nos	2 Nos	2 Nos	নাই
7.	Pendulum Arm; GYP40; Origin: China	2 Nos	2 Nos	2 Nos	নাই
8.	Water pool radiator; GYP40; Origin: China	2 Nos	2 Nos	2 Nos	নাই
9.	Lubricant Pump; GYP40; Origin: China	1 Nos	1 Nos	1 Nos	নাই
10.	Swing cylinder; GYP40; Origin: China	4 Nos	4 Nos	4 Nos	নাই
11.	Main pump; GYP40; Origin: China	1 Nos	1 Nos	1 Nos	নাই
12.	Upper and Lower spherical copper sleeve 2 upper 2 lower; GYP40; Origin: China	2 Nos	2 Nos	2 Nos	নাই
13.	140 mm cylinder; GYP40; Origin: China	1 Nos	1 Nos	1 Nos	নাই
14.	Planetary geared motor; GYP40; Origin: China	1 Nos	1 Nos	1 Nos	নাই
15.	Cycloidal pin wheel geared motor	2 Nos	2 Nos	2 Nos	নাই
16.	Planetary Cycloidal geared motor	2 Nos	2 Nos	2 Nos	নাই
17.	Cycloidal Geared motor	1 Nos	1 Nos	1 Nos	নাই
18.	Helical gearworn reducer	1 Nos	1 Nos	1 Nos	নাই
19.	Vertical Bavel reducer	1 Nos	1 Nos	1 Nos	নাই

পরিদর্শন রিপোর্ট ও স্বাক্ষরঃ পরীক্ষণ ও গ্রহণ কমিটি কর্তৃক ২৩/০৬/২০২৬ তারিখে সরবরাহকৃত মালামাল পরিদর্শন করা হল। মালামালের পরিমাণ সঠিক আছে, Technical specification অনুযায়ী যথাযথ আছে এবং গুণগত মান সন্তোষজনক; বিধায় সমুদয় মালামাল পরীক্ষণ ও গ্রহণ কমিটি কর্তৃক গৃহীত হ'ল।


২৩/০৬/২৬

মোঃ আল আমিন
নির্বাহী প্রকৌশলী

দাশেরকান্দি পয়ঃশোধনাগার ও
সদস্য-সচিব, পরীক্ষণ ও গ্রহণ কমিটি
ঢাকা ওয়াসা।


২৩/০৬/২৬

মোঃ মোমতাজুর রহমান
নির্বাহী প্রকৌশলী
পিএন্ডডি (তড়িৎ ও যান্ত্রিক)
ও
সদস্য, পরীক্ষণ ও গ্রহণ কমিটি
ঢাকা ওয়াসা।


২৩/০৬/২৬

মিজা মেলান কিবরিয়া
তত্ত্বাবধায়ক প্রকৌশলী
পানি ও পয়ঃশোধনাগার সার্কেল ও
আহবায়ক, পরীক্ষণ ও গ্রহণ কমিটি
ঢাকা ওয়াসা।

INSPECTION REPORT

Client : Ayesha Enterprise.

Tender ID : 1149370

Tender Name : Procurement of necessary Spare Parts such as piston, wire plate, s type switch valve, transfer valve, front end bearing seat, 140mm main cylinder, waterpull, radiator, main pump for plunger pump.

Description of Goods : 01 Unit Geard Motor, 01 Unit Geared Hoister & 01 Unit Gearworn Reducer

Inspection location : Dasherbandi STP Dhaka..

Inspection date : 18/07/2026

Scope of Inspection : 1. Visual quality check 2. Quantity check 3. Model no./ part no./ serial no. check4. SGS Witness Performance Test 5. Inspection Photo and Report Issuance

We, SGS Bangladesh Limited hereby report the following:

In accordance with instructions received from Ayesha Enterprise. SGS Inspector attended at the above-mentioned location and the date for conducting above mentioned inspection in presence of the representatives of Ayesha Enterprise. Inspection findings are given below:

Inspection Report Details:

On arrival at Dasherbandi STP Dhaka. on 18/07/2026, SGS' representative started the visual inspection and performance test of the Geard Motor, Geared Hoister & Gearworn Reducer. Details as following.

Equipment Details:

Equipment	Specification	Country of Origin	Unit	Quantity
Planetary Geared Motor	Brand Name: GUOMAO Type: BLDO-59-Y1.1 SI/No.: SN01672874	China	Set	01
Planetary Cycloidal Gear for Hoister	Brand Name: GUOMAO Type: ZSY160C-31.5I SI/No.: SN01672873	China	Set	01

Page 1 of 6

*This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/terms-and-conditions/> and, for Electronic format documents, subject to Terms and conditions for Electronic Documents at <https://www.sgs.com/en/terms-and-conditions/terms-e-document>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced, except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.



SGS BANGLADESH LIMITED

2nd, 6th to 10th & 13th Floors, Noor Tower, 110, Bir Uttam C.R. Datta Road, Dhaka-1205, G.P.O. Box No. 197, Bangladesh
t : +880 (0) 2 963 25 35, f : +880 (0) 2 963 25 42, e : lad.bangladesh@sgs.com, www.sgs.com

BDL 2940050

Member of the SGS Group (SGS SA)

Helical Gearworm Reducer	Brand Name: GUOMAO Type: GSA79-Y2.2-4P-130-M1-D50-270-IEC SI/No.: SN01672878	China	Set	01
--------------------------	--	-------	-----	----

Physical Findings:

During on site visit there were identified total 01 Unit Geard Motor, 01 Unit Geared Hoister & 01 Unit Gearworm Reducer. Goods were found inside a wooden crate. All itema visually checked and found okay without any visual damage.

Performance Test:

After installation performance parameters were checked through visual data display during operation conditions and found okay according to specification. Detail findings as below

Model/Serial Number of Inspected Items			Inspection Findings
Item Details	Model No.	Serial No./ TAG No.	
Planetary Geared Motor	BLDO-59-Y1.1	SN01672874	1. Brand name, Model no. Country of origin found okay. 2. No defects found during visual check. 3. Quantity found okay according to supplied documents. 4. Performance Test found okay
Planatray Cycloidal Gear for Hoister	ZSY160C-31.5I	SN01672873	
Helical Gearworm Reducer	GSA79-Y2.2-4P-130-M1-D50-270-IEC	SN01672878	

Tachometer Reading of Planetary Geared Motor				
Value mentioned in Specification (rpm)		Measured Value (rpm)		Remarks
Input Speed	1390 ± 5%	Input Speed	1430	Satisfactory considering the Tolerance
Output Speed	23.6 ± 5%	Output Speed	25.4	Satisfactory considering the Tolerance

Tachometer Reading of Helical Gearworm Reducer				
Value mentioned in Specification (rpm)		Measured Value (rpm)		Remarks

"This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/terms-and-conditions/> and, for Electronic format documents, subject to Terms and conditions for Electronic Documents at <https://www.sgs.com/en/terms-and-conditions/terms-e-document>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only



BDL 2940051

SGS BANGLADESH LIMITED


2nd, 8th to 10th & 13th Floors, Near Tower 110, Bir Uttam C.R. Datta Road, Dhaka-1205, G.P.O. Box No. 197, Bangladesh
t: +880 (0) 2 963 25 35, f: +880 (0) 2 963 25 42, e: lad.bangladesh@sgs.com, www.sgsbangladesh.com.bd

Member of the SGS Group (SGS SAI)

Input Speed	1410	Input Speed	-----	-----
Output Speed	11	Output Speed	11.4	Satisfactory considering the Tolerance

Conclusion : To the best of our knowledge and ability and as far as ascertained during inspection based on visual examination, ratio, speed, frequency, rated output, SGS Inspector is of the opinion that the inspected item 01 unit Planetary Geared Motor, 01 unit Planetary Cycloidal Gear for Hoister & 01 unit Helical Gearworm Reducer found in satisfactory condition.

Inspection Photo:



Planetary Geared Motor Visual Inspection

Planetary Geared Motor Visual Inspection

*This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/terms-and-conditions/> and for Electronic format documents, subject to Terms and conditions for Electronic Documents at <https://www.sgs.com/en/terms-and-conditions/terms-e-document>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.









BDL 2940052

SGS BANGLADESH LIMITED

2nd, 9th to 10th & 12th Floors, Near Tower 110, Bir Uttam C.R. Datta Road, Dhaka-1205, G.P.O. Box No. 197, Bangladesh
t: +880 (0) 2 963 25 35, f: +880 (0) 2 963 25 42, e: lad.bangladesh@sgs.com, www.sgs.com.bd

Member of the SGS Group (SGS SA)

Planetary Geared Motor Visual Inspection	Planetary Geared Motor Visual Inspection
	
Planatray Cycloidal Gear for Hoister Visual Inspection	Planatray Cycloidal Gear for Hoister Visual Inspection
	
Planatray Cycloidal Gear for Hoister Visual	Planatray Cycloidal Gear for Hoister Visual
	
Helical Gearworn Reducer Visual Inspection	Helical Gearworn Reducer Visual Inspection

"This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/terms-and-conditions/> and, for Electronic format documents, subject to Terms and conditions for Electronic Documents at <https://www.sgs.com/en/terms-and-conditions/terms-e-document>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.




SGS BANGLADESH LIMITED

2nd, 6th to 10th & 13th Floors, Noor Tower, 110, Bir Uttam C.R. Datta Road, Dhaka-1205, G.P.O. Box No. 197, Bangladesh
t : +880 (0) 2 963 25 35, f : +880 (0) 2 963 25 42, e : lad.bangladesh@sgs.com, www.sgsgroup.com bd

BDL 2940053

Member of the SGS Group (SGS SA)



	
Helical Gearworm Reducer Visual Inspection	Helical Gearworm Reducer Visual Inspection
	
Performance Test of Planetary Geared Motor	Performance Test of Planetary Geared Motor
	
Performance Test of Cycloidal Gear for Hoister	Performance Test of Cycloidal Gear for Hoister

*This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/terms-and-conditions/> and for Electronic format documents, subject to Terms and conditions for Electronic Documents at <https://www.sgs.com/en/terms-and-conditions/terms-a-document>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein refers to the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.




SGS BANGLADESH LIMITED

BDI 2940054

2nd, 6th to 10th & 13th Floors, Nakk Tower 110, Bir Uttam C.R. Datta Road, Dhaka 1205, G.P.O. Box No. 197, Bangladesh
t: +880 (0) 2 963 25 35 f: +880 (0) 2 963 25 42 e: info.bangladesh@sgs.com www.sgsbangladesh.com www.sgs.com

Member of the SGS Group (SGS SA)



The above reflects our findings at the date and place of intervention only. The inspection was done to the best of our knowledge and ability and due care. The inspection done and report issued does not absolve the seller / manufacturer from their contractual obligations towards their buyer nor does it prejudice buyer's right of claim toward seller /suppliers for compensation for any apparent and/or hidden defects during our inspection or occurring thereafter.

This report comprises of 06 (Six) pages and is not valid for negotiation unless bear the following signature.

THIS REPORT IS ISSUED WITHOUT PREJUDICE TO ANY AND ALL PARTIES CONCERNED.

Shakim
SGS BANGLADESH LIMITED

Page 6 of 6

*This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/terms-and-conditions/> and for Electronic format documents, subject to Terms and conditions for Electronic Documents at <https://www.sgs.com/en/terms-and-conditions/terms-e-document>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only

SGS BANGLADESH LIMITED

BDL 2940055

2nd, 8th to 10th & 13th Floors, Noor Tower, 110, Bir Uttam C.R. Datta Road, Dhaka-1205, G.P.O. Box No. 197, Bangladesh
t: +880 (0) 2 963 25 35, f: +880 (0) 2 963 25 42, e: bd.bangladesh@sgs.com, www.sgsgroup.com/bd

Member of the SGS Group (SGS SA)



Inspection Report

(Non-negotiable)

Inspector: Herbert Fan
Inspection location: Tai An City, Shandong Province, China
Date of inspection: Apr. 21&22, 2026



SGS-CSTC (Shanghai) Technical Services (Shanghai) Co., Ltd.
Inspection & Testing Services

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Building 9, No 69, Block 1150, East Kangqiao Road, Pudong District, Shanghai, China 201319

中国·上海·浦东康桥东路1159弄69号9号楼

邮编: 201319

t (86-021) 6119 6300

www.sgsgroup.com.cn

t (86-021) 6119 6300

sgs.china@sgs.com



Contents

1. Background information	3
2. Instrument	3
3. Quantity check	4
4. Marking check	Error! Bookmark not defined.
5. Visual quality check	7
6. Dimension check	Error! Bookmark not defined.
7. Witness testing	Error! Bookmark not defined.
8. Document Verification	Error! Bookmark not defined.
9. Photos	8
10. Timesheet	16



SGS-CTSC (Shanghai Technical Services Co., Ltd.)
Industrial Service

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Qeccheck@sgs.com

Building 9, No 69, Block 1159, East Kangqiao Road, Pudong District, Shanghai, China 201319

中国·上海·浦东康桥东路1159弄69号9号楼 邮编: 201319

t (86-021) 6119 6300 www.sgs.com.cn

t (86-021) 6119 6300 sgs.china@sgs.com



1. Background information

SGS order No.:	SHINSCS2600299R01				
Coordinator:	Angela Zhuang	Telephone:	+86 (021) 68183170		
Description of commodity (Name ,Model ,Quantity ...)					
Pump, Motor and other items					
Buyer(Name ,Address...)					
Ayesha Enterprise 166, East Tejtori Bazar, Tejgaon, Dhaka, Bangladesh					
Seller(Name ,Address...)					
Taian Sanli Environmental Protection Technology Co., Ltd. Dayao District, Beijizuoapao Subdistrict, Zhongtianmen Street, Taian City, Shandong Province					
P/I No.	WSL200125	Date:	20-Feb-2026		
LC No.	N/A				
Others	N/A				
Nature of inspection:	Item	Satisfactory		Non conforming	
	Quantity check(not include weight check)	●			
	Item	Satisfactory	Non conforming	Rejected	Subject to buyer's evaluation
	Specification check				●
	Visual quality check	●			
	Document Review				●

2. Instrument

During the inspection, the following instrument calibration status has been checked for inspection:

No.	Name	ID No.	Measuring range	Calibrated ^[1] (Yes/No/NA)	Certificate NO.
1	/	/	/	/	/
2					

[1] Calibrated

— "Yes" means the instrument was calibrated and now is in the period of validity.



SGS-CSTC (Shanghai) Technical Services Co., Ltd.
Industries Service

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Qcscheck@sgs.com

Building 8, No 68, Block 1150, East Kangqiao Road, Pudong District, Shanghai, China 201319

中国·上海·浦东康桥东路1159弄69号9号楼 邮编: 201319

t(86-021) 6119 6300 www.sgs.com.cn

t(86-021) 6119 6300 sgs.china@sgs.com



— "No" means the instrument should be calibrated, in fact it was never calibrated or not calibrated before the expiry date.

— "NA" means the instrument does not need to be calibrated in the view of its function.

3. Quantity check and Specification check (brand name/ model no./ country of origin/ manufacturing year/ serial no.)

3.1. Reference documents:

→ WSL Proforma (Production list)

3.2. Method of quantity check

→ Total quantity counting

No.	Description	Specification check	Req./Act. Quantity	Remark
1	S type Switch Valve for Plunger Pump. (S 转换阀) Plunger Pump Model: GYP40. Origin: China.	Brand: Sanli Model No.: GYP40 Origin: China Manufacture Year: Apr. 2026 Serial No.: NA	2/2	Remark 1
2	Transfer Valve Front End Bearing Seat Including Seal for Plunger Pump. (前端轴承座,含密封) Plunger Pump Model: GYP40. Origin: China	Brand: Sanli Model No.: GYP40 Origin: China Manufacture Year: Apr. 2026 Serial No.: NA	2/2	Remark 1
3	Transfer Valve Front Rear Bearing Seat Including Seal for Plunger Pump. (后端轴承座,含密封) Plunger Pump Model: GYP40. Origin: China	Brand: Sanli Model No.: GYP40 Origin: China Manufacture Year: Apr. 2026 Serial No.: NA	2/2	Remark 1
4	Piston for Plunger Pump. (活塞) Plunger Pump Model: GYP40. Origin: China	Brand: Sanli Model No.: GYP40 Origin: China Manufacture Year: Apr. 2026 Serial No.: NA	2/2	Remark 1
5	Wear Plate for Plunger Pump. (耐磨板) Plunger Pump Model: GYP40. Origin: China	Brand: Sanli Model No.: GYP40 Origin: China	2/2	Remark 1



SGS-CTC (Shanghai) Technical Services Co., Ltd.
Industries Service

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's Instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing/inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Qcscheck@sgs.com

Building 9, No 69, Block 1158, East Kangqiao Road, Pudong District, Shanghai, China 201319
中国·上海·浦东康桥东路1159弄69号9号楼 邮编: 201319

t:(86-021) 6119 6300 www.sgs.com.cn
t:(86-021) 6119 6300 sgs.china@sgs.com



		Manufacture Year: Apr. 2026 Serial No.: NA		
6	Wear Ring for Plunger Pump. (耐磨环) Plunger Pump Model: GYP40. Origin: China	Brand: Sanli Model No.: GYP40 Origin: China Manufacture Year: Apr. 2026 Serial No.: NA	2/2	Remark 1
7	Pendulum/Rocket Arm. Plunger Pump Model: GYP40. Origin: China	Brand: Sanli Model No.: GYP40 Origin: China Manufacture Year: Apr. 2026 Serial No.: NA	2/2	Remark 1
8	Water Pool Radiator for Plunger Pump. (水冷散热器) Plunger Pump Model: GYP40. Origin: China	Brand: Ningbo Tianyuan Model No.: GYP40 Origin: China Manufacture Year: Apr. 2026 Serial No.: NA	2/2	Remark 1
9	Lubricant Pump for Plunger Pump. (电动润滑泵) Plunger Pump Model: GYP40. Origin: China	Brand: Sanli Model No.: GYP40 Origin: China Manufacture Year: Apr. 2026 Serial No.: NA	1/1	Remark 1
10	Swing / Sludge Cylinder for Plunger Pump. (摆缸) Plunger Pump Model: GYP40. Origin: China	Brand: Sanli Model No.: GYP40 Origin: China Manufacture Year: Apr. 2026 Serial No.: NA	4/4	Remark 1
11	Main Pump for Plunger Pump. (主泵) Plunger Pump Model: GYP40. Origin: China	Brand: Sanli Model No.: GYP40 Origin: China Manufacture Year: Apr. 2026 Serial No.: NA	1/1	Remark 1
12	Upper and Lower Spherical Copper Sleeve 2 Upper 2 Lower for Plunger Pump. (球形铜套) Plunger Pump Model: GYP40. Origin: China	Brand: Sanli Model No.: GYP40 Origin: China Manufacture Year: Apr. 2026 Serial No.: NA	2/2	Remark 1



SGS-CSI (Shanghai) Technical Services (Shanghai) Co., Ltd.
Industries Service

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 6307 1443, or email: CN.Doccheck@sgs.com

Building 9, No 69, Block 1150, East Kangqiao Road, Pudong District, Shanghai, China 201319

中国·上海·浦东康桥东路1159弄69号9号楼

邮编: 201319

t(86-021) 6119 6300

www.sgs.com

t(86-021) 6119 6300

sgs.china@sgs.com



13	140 mm Cylinder for Plunger Pump. (主缸) Plunger Pump Model: GYP40. Origin: China	Brand: Sanli Model No.: GYP40 Origin: China Manufacture Year: Apr. 2026 Serial No.: NA	1/1	Remark 1
14	Planetary Geared Motor for Star-unloader. (布袋星 型卸料机, 带电机) Model: BLD0-59-Y1.1-ZP IEC, Brand :GUOMAO, Origin:China.	Brand: GUOMAO Model No.: BLD0-59-Y1.1-ZP IEC Origin: China Manufacture Year: Mar. 2026 Serial No.: SN01672874	1/1	N/A
15	Cycloidal Pin Wheel Geared Motor for Chain Conveyer. (链运机的减速机, 带电机) Model: BWD4-71-Y5.5-ZP IEC, Brand :GUOMAO, Origin:China.	Brand: GUOMAO Model No.: BWD4-71-Y5.5 Origin: China Manufacture Year: Mar. 2026 Serial No.: SNO1672875 SNO1672875	2/2	N/A
16	Planetary Cycloidal Gear for Hoister. (斗提机减速 机, 不带电机) Model: ZSY160-31.5-I, Brand :GUOMAO, Origin:China.	Brand: GUOMAO Model No.: ZSY160-31.5-I Origin: China Manufacture Year: Mar. 2026 Serial No.: SN01672872 SN01672873	2/2	N/A
17	Cycloidal Geared Motor for Sludge, Slurry Mixer. (调泥缸 用减速机, 带电机) Model: BWD5-35-Y15-ZP IEC, Brand :GUOMAO, Origin:China.	Brand: GUOMAO Model No.: BWD5-35-Y15-ZP IEC Origin: China Manufacture Year: Mar. 2026 Serial No.: SN01672877	1/1	N/A
18	Helical Gearworm Reducer with Motor for Drying Tower Star-fedder. (干化塔卸料减 速机带电机) Brand: GUOMAO, Origin: China. Model: GSA7Z-Y2.2-4P-130-M1-D50-270-ZPIEC	Brand: GUOMAO Model No.: GSA79-Y2.2-4P-130-M1-D50- 270-ZPIEC Origin: China Manufacture Year: Mar. 2026 Serial No.: SN01672878	1/1	N/A
19	Vertical Bavel Reducer for Drying Tower Dust	Brand: GUOMAO	1/1	Remark 2



SGS-CTC (Shanghai) Technical Services Co., Ltd.
Industries Service

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's Instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing/inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Building 9, No 68, Block 1150, East Kangqiao Road, Pudong District, Shanghai, China 201319

中国·上海·浦东康桥东路1159弄69号9号楼

邮编: 201319

t:(86-021) 6119 6300

www.sgs.com.cn

t:(86-021) 6119 6300

sgs.china@sgs.com



Scraper. (干化塔刮刀用减速机, 不带电机) Model: V4SV6-200-D-BPD4, Brand :GUOMAO, Origin:China.	Model No.: B406SV-200-D-DPB Origin: China Manufacture Year: Mar. 2026 Serial No.: NA		
Total		33/33	

3.3. Remark 1. Nameplate printed as A4 paper and set in package. No serial No. Was found, Sanli explained that these items are general components of equipment, no serial number requirement. No manufacture date was found, Sanli explained that these items were manufacture in Apr. 2026.

3.4. Remark 2. For item 19, WSL proforma list model: V4SV6-200-D-BPD4, actual Model: B406SV-200-D-DPB. After Sanli clarified with Guomao, Guomao stated as below:


The Guomao reducer PV series has now been fully rebranded as the HB series. The previous model: V4SV6-200-D-DPB4 is now represented by the new model. For: B406SV-200-D-DPB. The attached drawings indicate the new model designation and ensure the correct installation dimensions.

Model designation explanation.

The Guomao reducer PV series has now been fully rebranded as the HB series. The previous model: V4SV6-200-D-DPB4 is now represented by the new model.

For: B406SV-200-D-DPB. The attached drawings indicate the new model designation and ensure the correct installation dimensions.

译: 国茂减速机 PV 系列现在全系改名为 HB 系列, 原型号 V4SV6-200-D-DPB4 或型号表达为 B406SV-200-D-DPB。下附为标图为新型号表示, 且保证安装尺寸。



3.5. Remark: The result of quantity check is compliant with packing list, result was satisfactory.

3.6 Specification check (brand name/ model no./ country of origin/ manufacturing year/ serial no.) is subjected to buyer' s evaluation.

4. Visual quality check

4.1. Sample size: 100%



SGS-CSI (Shanghai) Technical Services (Shanghai) Co., Ltd.
Industries Service

IND-F-OPS-05-21 [V: 04, Apr 28th, 2023]

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Qccheck@sgs.com

Building 9, No 69, Block 1159, East Kangqiao Road, Pudong District, Shanghai, China 201319

中国·上海·浦东康桥东路1159弄69号9号楼

邮编: 201319

t:(86-021) 6119 6300

t:(86-021) 6119 6300

www.sgs.com

sgs.china@sgs.com

Member of the SGS Group (SGS SA)



During the inspection, visual quality was performed by SGS inspector, inspector had checked top sides. Details as follows:

- The items listed above were all brand new and show no signs of having been used.
- No damage or obvious defect was found on material surface or coated surface.


4.2. Remark: The result of visual quality check was satisfactory.

5. All FAT reference documents reviewed with SGS stamp & sign


5.1. During the inspection, no FAT document was present for review.

5.2. Remark: The result of document review was subjected to Subject to buyer's evaluation.

6. Photos



Overall production and packages



Overall production and packages



SGS-CSTC (Shanghai) Technical Services Co., Ltd.
Industries Service

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Check@sgs.com

Building 9, No 69, Block 1159, East Kangqiao Road, Pudong District, Shanghai, China 201319

中国·上海·浦东康桥东路1159弄69号9号楼

邮编: 201319


t:(86-021) 6119 6300

www.sgs.com.cn


t:(86-021) 6119 6300

sgs.china@sgs.com


SGS




No. 1 - S type Switch Valve for Plunger Pump.



No. 1 - S type Switch Valve for Plunger Pump.



No. 2 - Transfer Valve Front End
Bearing Seat Including
Seal for Plunger Pump.



No. 3 - Transfer Valve Front Rear
Bearing Seat Including
Seal for Plunger Pump.



SGS-CHINA Inspection & Testing Services Co., Ltd.
Industries Service

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.


Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing/inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com


Building 8, No 69, Block 1159, East Kangqiao Road, Pudong District, Shanghai, China 201319
中国·上海·浦东康桥东路1159弄69号9号楼 邮编: 201319

(86-021) 6119 6300 www.sgs.com
(86-021) 6116 6300 sgs.china@sgs.com


SGS




No. 4 - Piston for Plunger Pump.



No. 5 - Wear Plate for Plunger Pump.



No. 6 - Wear Ring for Plunger Pump.



No. 7 - Pendulum/Rocket Arm for Plunger Pump.



SGS-OSTC (Shanghai) Technical Services Co., Ltd.
Industries Service

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's Instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing/inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Building 9, No 69, Block 1158, East Kangqiao Road, Pudong District, Shanghai, China 201319
中国·上海·浦东康桥东路1159弄69号9号楼 邮编: 201319

t:(86-021) 6119 6300 www.sgsgroup.com.cn
t:(86-021) 6119 6300 sgs.china@sgs.com


SGS




No. 8 - Water Pool Radiator for
Plunger Pump.



No. 8 - Water Pool Radiator for
Plunger Pump. nameplate



No. 9 - Lubricant Pump for
Plunger Pump.



No. 10 - Swing / Sludge Cylinder for Plunger Pump.



SGS-CSTC (Shanghai) Technical Service Co., Ltd.
Industries Service

IND-F-OPS-05-21 [V: 04, Apr 28th, 2023]

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing/inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Building 9, No 69, Block 1159, East Kangqiao Road, Pudong District, Shanghai, China 201319

中国·上海·浦东康桥东路1159弄69号9号楼

邮编: 201319

t: (86-021) 6119 6300


www.sgs.com.cn

t: (86-021) 6119 6300


sgs.china@sgs.com

Member of the SGS Group (SGS SA)

SGS




No. 11 - Main Pump for Plunger Pump.



No. 12 - Upper and Lower Spherical Copper Sleeve 2
Upper 2 Lower for Plunger Pump.



No. 13 - 140 mm Cylinder for Plunger Pump.



Sample-Nameplate printed as A4 paper in packages



SGS-CSTC (Shanghai) Technical Service Co., Ltd.
Industries Service

IND-F-OPS-05-21 [V. 04, Apr 26th, 2023]

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Detectcheck@sgs.com

Building 9, No 69, Block 1150, East Kangqiao Road, Pudong District, Shanghai, China 201319
中国·上海·浦东康桥东路1159弄69号9号楼 邮编: 201319


t:(86-021) 6119 6300 www.sggagroup.com.cn
f:(86-021) 6119 6300 sgs.china@sgs.com

Member of the SGS Group (SGS SA)


SGS




No. 14 - Planetary Geared Motor
for Star-unloader., IP55F-380V



No. 14 - Planetary Geared Motor
for Star-unloader, IP55F-380V nameplate



No. 15 Cycloidal Pin Wheel
Geared Motor for Chain
Conveyer. IP55F-380V, 50HZ



No. 15 Cycloidal Pin Wheel
Geared Motor for Chain
Conveyer. IP55F-380V 50HZ nameplate



IND-F-OPS-05-21 [V: 04, Apr26th, 2023]

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Descheck@sgs.com

Building 9, No 60, Block 1158, East Kangqiao Road, Pudong District, Shanghai, China 201319

中国·上海·浦东康桥东路1158弄69号9号楼

邮编: 201319

t (86-021) 6119 6300


www.sgs.com

t (86-021) 6119 6300


sgs.china@sgs.com

Member of the SGS Group (SGS SA)

SGS



No. 15 Cycloidal Pin Wheel
Geared Motor for Chain
Conveyer. IP55F-380V, 50HZ



No. 15 Cycloidal Pin Wheel
Geared Motor for Chain
Conveyer.) IP55F-380V, 50HZ nameplate



No. 16 - Planetary Cycloidal Gear
for Hoister.



No. 16 - Planetary Cycloidal Gear
for Hoister. nameplate



SGS-CHINA Inspection & Testing Services
Impressaries Service

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.


Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 6307 1443, or email: CN.Doscheck@sgs.com

Building 9, No 69, Block 1150, East Kangqiao Road, Pudong District, Shanghai, China 201319
中国·上海·浦东康桥东路1159弄69号9号楼 邮编: 201319

t(86-021) 6119 6300 www.sgs.com
t(86-021) 6119 6300 sgs.china@sgs.com


SGS



No. 16 - Planetary Cycloidal Gear
for Hoister.



No. 16 - Planetary Cycloidal Gear
for Hoister. nameplate



No. 17 - Cycloidal Geared Motor
for Sludge, Slurry Mixer. IP55F-380V, 变频电机 50HZ



No. 17 - Cycloidal Geared Motor
for Sludge, Slurry Mixer. IP55F-380V, 变频电机 50HZ nameplate



SGS-CTSC (Shanghai Technical Services) Co., Ltd.
Industries Service

IND-F-OPS-05-21 [V: 04, Apr 28th, 2023]

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Descheck@sgs.com

Building 9, No 69, Block 1159, East Kangqiao Road, Pudong District, Shanghai, China 201319
中国·上海·浦东康桥东路1159弄69号9号楼 邮编: 201319

t: (86-021) 6119 6300 www.sgsgroup.com.cn
t: (86-021) 6119 6300 sgs.china@sgs.com

Member of the SGS Group (SGS SA)


SGS




No. 18 - Helical Gearworm Reducer
with Motor for Drying
Tower Star-fedder. IP55F-380V



No. 18 - Helical Gearworm Reducer
with Motor for Drying
Tower Star-fedder. IP55F-380V nameplate



No. 19 - Vertical Bavel Reducer for
Drying Tower Dust
Scraper. IP55F-380V



No. 19 - Vertical Bavel Reducer for
Drying Tower Dust
Scraper. IP55F-380V nameplate

7. Timesheet

Name/Date	Time	Description	Hours
Herbert Fan Apr.21, 2026	7:30-11:30	Traveling(800km)	4
	12:00-16:30	Working	4
Apr.22, 2026	8:00-10:30	Working and Report	4



SGS-CTSC (Shanghai) Technical Services (Shanghai) Co., Ltd.
Industries Service

IND-F-OPS-05-21 [V: 04, Apr 28th, 2023]

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 6307 1443, or email: CN.Descheck@sgs.com

Building 9, No 69, Block 1158, East Kangqiao Road, Pudong District, Shanghai, China 201319

中国·上海·浦东康桥东路1159弄69号9号楼

邮编: 201319

t (86-021) 6119 6300

www.sgs.com.cn

t (86-021) 6119 6300

sgs.china@sgs.com

Member of the SGS Group (SGS SA)

SGS

	12:00-16:30	Traveling(800km)	4
Total			16

Note: Both traveling time and reporting time are included.

THIS REPORT ONLY REFLECTED OUR ACTUAL FINDINGS. THE INSPECTION WAS DONE TO THE BEST OF OUR KNOWLEDGE AND ABILITY AND WITH DUE CARE. THE FINDINGS ARE VALID AS FOR TIME AND PLACE OF INSPECTION.

Issued by:	<i>Herbert Jiao</i>	Reviewed by:	<i>Angela Zhang</i>	Approved by:	<i>WJ</i>
Title or position:	Inspector	Title or position:	Coordinator	Title or position:	Inspection Manager
Date:	April 23, 2026	Date:	April 24, 2026	Date:	April 24, 2026

End of Report



SGS-OSTC Inspection & Testing Services (Shanghai) Co., Ltd.
Industries Service

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at <https://www.sgs.com/en/terms-and-conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8367 1443, or email: CN.Docscheck@sgs.com

Building 9, No 69, Block 1159, East Kangqiao Road, Pudong District, Shanghai, China 201319

中国·上海·浦东康桥东路1159弄69号9号楼

邮编: 201319

t:(86-021) 6119 6300

www.sgsgroup.com.cn

t:(86-021) 6119 6300

sgs.china@sgs.com