



ঢাকা পানি সরবরাহ ও পয়ঃ নিষ্কাশন কর্তৃপক্ষ

৩০

নির্বাহী প্রকৌশলীর কার্যালয়
দাশেরকান্দি পয়ঃশোধনাগার
আফতাবনগর, খিলগাঁও, ঢাকা-১২১৯।

পরীক্ষণ ও গ্রহণ কমিটির রিপোর্ট

কাজের নাম	ঃ Supply of Stator & Rotor of Dehydrator Sewer Mud Pump for maintenance of Sludge Thickening and Dewatering system of Dasherakandi STP.
কার্যাদেশ নং-	ঃ ৪৬.১১৩.৬৩৭.০০.০০.০৩৪.২০২৫-১০৫৩; তারিখঃ ১২/০৩/২০২৬।
ঠিকাদারী প্রতিষ্ঠানের নাম	ঃ Integral solutions
ব্যবহারকারী বিভাগের নাম	ঃ দাশেরকান্দি পয়ঃশোধনাগার।
সরবরাহের স্থান	ঃ প্ল্যান্টের উপ-ভান্ডার।
সরবরাহের তারিখ	ঃ ২৯/০৬/২০২৬ইং।
পরিদর্শনের তারিখ	ঃ ৩০/০৬/২০২৬ইং

ক্রঃ নং	মালামালের বিবরণ	চুক্তি অনুযায়ী মালামাল ও কাজের পরিমাণ	একই কিস্তিতে প্রদেয় মালামাল ও সম্পাদিত কাজের পরিমাণ	একই কিস্তিতে গ্রহণযোগ্য মালামালের পরিমাণ	বাতিলকৃত মালামালের পরিমাণ
1.	ROTOR, Code No.: 60/70-6L, Item No.: 600 (Pump Model: BN70-6L)	5 Nos	5 Nos	5 Nos	নাই
2.	STATOR, Code No.: 60/70-6L, Item No.: 601 (Pump Model: BN70-6L)	5 Nos	5 Nos	5 Nos	নাই
3.	Single set joint parts 060/35 NBR 30321 One Joint kit includes 1x 401 - retaining sleeve; 1x 402 - coupling rod pin; 2x 403 - guide bushing; 1x 404 - coupling rod bushing; 1x 405 - universal joint sleeve; 1x 406 - large holding band; 1x 407 - small holding band; 1x 4 ounce bottle of joint grease This set contains the pin joint grease type 30321	3 Set	3 Set	3 Set	নাই

পরিদর্শন রিপোর্ট ও স্বাক্ষরঃ পরীক্ষণ ও গ্রহণ কমিটি কর্তৃক ৩০/০৬/২০২৬ তারিখে সরবরাহকৃত মালামাল পরিদর্শন করা হল। মালামালের পরিমাণ সঠিক আছে, Technical specification অনুযায়ী যথাযথ আছে এবং গুণগত মান সন্তোষজনক; বিধায় সমুদয় মালামাল পরীক্ষণ ও গ্রহণ কমিটি কর্তৃক গৃহীত হ'ল।


30/06/26

মোঃ আল আমিন
নির্বাহী প্রকৌশলী
দাশেরকান্দি পয়ঃশোধনাগার ও
সদস্য-সচিব, পরীক্ষণ ও গ্রহণ কমিটি
ঢাকা ওয়াসা।


30/06/26

মোঃ মোমতাজুর রহমান
নির্বাহী প্রকৌশলী
পিএন্ডডি (তড়িৎ ও যান্ত্রিক)
ও
সদস্য, পরীক্ষণ ও গ্রহণ কমিটি
ঢাকা ওয়াসা।


30/06/26

মির্জা গোলাম কিবরিয়া
তত্ত্বাবধায়ক প্রকৌশলী
পানি ও পয়ঃশোধনাগার সার্কেল ও
আহবায়ক, পরীক্ষণ ও গ্রহণ কমিটি
ঢাকা ওয়াসা।

Original


SGS

INSPECTION REPORT

SGS Germany GmbH
Heidenkampsweg 99
D-20097 Hamburg

SGS Germany Report No.: 7845413#10A
Customer Reference No.:

SGS INSPECTION REPORT			
SGS Report No.	7845413#10A	Revision	1
CUSTOMER INFORMATION			
Customer	Integral Solutions, Add:374/1, West Rampura, Dhaka	Project	Office of the EE, Dasherhendi Sewage Treatment Plant, Dhaka WASA
Customer Ref. No.	46.113.637.00.00.045.2024/ Notice-R110, ID-No.:1177821	Customer Contact	
SUPPLIER / MANUFACTURER INFORMATION		PLACE OF INSPECTION	
Company	SEEPEX GmbH	Company	SEEPEX GmbH
Location	Scharnhölzstraße 344, 46240 Bottrop	Location	Scharnhölzstraße 344, 46240 Bottrop
Contact Name	Mr. Torsten Kollander	Contact Name	Mr. Torsten Kollander
Phone	+49 2041-996 -4638	Phone	+49 2041-996 -4638
Email	Thorsten.kollender@irco.com	Email	Thorsten.kollender@irco.com
INSPECTION DETAILS			
Scope of Inspection	Visual Inspection (Quantity, Quality, Specification check and documents review)		
Equipment inspected	Spare Parts (Rotor and Stator)		
SGS Inspector	Jürgen Prott	Reporting Date	05.06.2026
Visit Date(s)	05.06.2026		
SGS Germany Coordinator	Mr. L. Liwschitz	Coordinator E-mail	Leonid.liwschitz@sgs.com
ATTENDEES			
Name	Company	Phone	E-Mail
Mr. Torsten Kollander	SEEPEX	+49 2041-996 -174	Thorsten.kollender@irco.com
Mr. Jürgen Prott	SGS	+49 15752689768	juergen.prott@sgs.com
OVERALL INSPECTION RESULT			
Satisfactory			
REMARKS			
None			



Member of the SGS Group (Société Générale de Surveillance)

Issued by: Oliver Francois
Title: Technical Manager

Date: 22.10.2021
Version: 04

Annex 1.1.2 SOP O 180

Page 1 of 8

INSPECTION REPORT

SGS Germany GmbH
Heidenkampsweg 99
D-20097 Hamburg

SGS Germany Report No.: 7845413#10A
Customer Reference No.:

1. EQUIPMENT DETAILS

PO Item No.	Serial / TAG No.	Qty	Product Description
1	Item No.:600	5	Rotor 60/70-6L (Pump Model BN 70-6L)
2	ItemNo.601	5	Stator 60/70-6L NBR TSE (P-Model BN 70-6L)
3	Kit	3	Single set joint parts 060/35 NBR

2. DOCUMENTS USED DURING INSPECTION

Document Name	Document No.	Revision No.	Issue Date
Draft: Certificate of Origin	40261814	0	22.12.2025
Technical Standart			
Price schedule			
Auftrag	100178738		15.05.2026
Technical Compliance			10.02.2026

3. MEASURING EQUIPMENT / INSTRUMENTS USED

Instrument	Instrument No.	Calibration certificate	Validity date	Appropriate for required use?
N.A	Klicken oder tippen Sie hier, um Text einzugeben.			Yes X No ☐

4. SUMMARY OF INSPECTION

Equipment Description / Tag No.	Activities Performed	Result
Rotor, Stator, Accessories	Visual Inspection - (Quantity, Quality, Specification check and documents review)	Satisfactory

Member of the SGS Group (Société Générale de Surveillance)

Issued by: Oliver Francois
Title: Technical Manager

Date: 22.10.2021
Version: 04

Annex 1.1.2 SOP O 180

Page 2 of 8



SGS Germany GmbH
Heidenkampsweg 99
D-20097 Hamburg

INSPECTION REPORT

SGS Germany Report No.: 7845413#10A
Customer Reference No.:

5. BRIEF DESCRIPTION OF INSPECTIONS PERFORMED

5.1 Inspection and Tests required

- Visual inspection, including Quantity, Quality, Specification check, Comparison with documents.

5.2 Activities performed

The complete order were presented in the production area by SEEPEX GmbH in Bottrop.

5.2.1 Visual inspection, quantity and quality check, specification check, check according to documents.

The rotors and stators passed the inspection according to the documents.

The visual inspection regarding design, workmanship and marking appearance and finish was found to be satisfactory. No fissure or other damage was ascertained. The rotors will be repainted before delivery.

The type, quantity and completeness were checked according to the above documents.

The kits were checked for completeness (retaining sleeve, coupling rod pin, guide bushings, joint sleeve, holding band and joint grease). According to the list (Certificate of Origine), there are only 8 parts.

Results: Satisfactory

6. DOCUMENT REVIEW:

Document Name	Document No.	Revision No.	Issue Date	Result
---------------	--------------	--------------	------------	--------

7. DEVIATIONS / NON CONFORMITIES:

No.	Equipment Description / Tag No.	Deviation description
		NONE

8. ATTACHMENTS

See item 2

Member of the SGS Group (Société Générale de Surveillance)

Issued by: Oliver Francois

Date: 22.10.2021

Page 3 of 8

Title: Technical Manager

Version: 04

Annex 1.1.2 SOP O 180

SGS Germany GmbH
Heidenkampsweg 99
D-20097 Hamburg

SGS Germany Report No.: 7845413#10A
Customer Reference No.:

9. DISCLAIMER

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

In accordance with Client's instructions, the Company's involvement has been limited to witnessing/observing a third party's intervention(s) at the third party's laboratory/test house or other facilities and installations used for the intervention(s). The Company's sole responsibility was to be present at the time of the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is not responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied, the qualifications, actions or omissions of the third party's personnel or the analysis results.

The publication and duplicating of our test reports and expert opinions for advertising purposes as well as their use for any other purposes in extracts requires our written approval.

Member of the SGS Group (Société Générale de Surveillance)

Issued by: Oliver Francois

Date: 22.10.2021

Page 4 of 8

Title: Technical Manager

Version: 04

Annex 1.1.2 SOP O 180

SGS Germany GmbH
Heidenkampsweg 99
D-20097 Hamburg

INSPECTION REPORT

SGS Germany Report No.: 7845413#10A
Customer Reference No.:

10. PHOTOGRAPHS taken during inspection

No.	Description	Photo
10.1	Overview Rotor	
10.2	Overview stator and spare parts boxes	

Member of the SGS Group (Société Générale de Surveillance)

Issued by: Oliver Francois

Date: 22.10.2021

Page 5 of 8

Title: Technical Manager

Version: 04



Annex 1.1.2 SOP O 180



SGS Germany GmbH
Heidenkampsweg 99
D-20097 Hamburg

INSPECTION REPORT

SGS Germany Report No.: 7845413#10A
Customer Reference No.:

10.3	Example for rotor marking	
10.4	Example for stator marking	
10.5	Inside stator	

Member of the SGS Group (Société Générale de Surveillance)

Issued by: Oliver Francois
Title: Technical Manager

Date: 22.10.2021
Version: 04

Annex 1.1.2 SOP O 180

INSPECTION REPORT

SGS Germany GmbH
Heidenkampsweg 99
D-20097 Hamburg

SGS Germany Report No.: 7845413#10A

Customer Reference No.:

10.6 Example for dimensional control



10.7 Example for spare part



10.8 Example for spare part in the box



Member of the SGS Group (Société Générale de Surveillance)

Issued by: Oliver Francois

Date: 22.10.2021

Page 7 of 8

Title: Technical Manager

Version: 04

Annex 1.1.2 SOP O 180

SGS

Original

INSPECTION REPORT

SGS Germany GmbH
Heidenkampsweg 99
D-20097 Hamburg

SGS Germany Report No.: 7845413#10A
Customer Reference No.:

Date: 15.06.2026

Date: 15.06.2026

SGS
i.A. **SGS Germany GmbH**
Heidenkampsweg 99 - 20097 Hamburg

Matthias Ruprecht
Customer Service SCS
SGS Germany GmbH

SGS
i.A. **SGS Germany GmbH**
Heidenkampsweg 99 - 20097 Hamburg

Leonid Liwschitz
Customer Service SCS
SGS Germany GmbH

END OF REPORT

Member of the SGS Group (Société Générale de Surveillance)

Issued by: Oliver Francois
Title: Technical Manager

Date: 22.10.2021
Version: 04

Annex 1.1.2 SOP O 180

Page 8 of 8