

Ref: IT-Bill-WASA-21042026-01

April 21, 2026

To,
Senior System Analyst
MIS & Billing Department
WASA Bhaban, Kawran Bazar,
Dhaka WASA. Dhaka-1216.

Handwritten: Paid
Signature: Alex
Date: 21.04.26

Sub: Bill for Service Machine & Under Pump House Covered List of Different Pump House under MODS Zone 2, 3 and 4.

Dear Sir,
Regarding the previously mentioned subject, I am pleased to inform you that we have successfully Repair, Maintenance with Spare Parts and installed the mentioned pump houses in accordance with your specifications. Kindly proceed with the settlement of the invoice.

BILL

S/L	PRODUCE/ SPARES DESCRIPTION	Device Location/ Pump Houses	Zone / Offices	QTY.	UNIT PRICE	TOTAL PRICE
1.	1. Finger Sensor-1 Pc 2. Adapter-01 Pc 3. Base-1 Pc	Rohamotullah School Pump	MODS Zone-2	01 Set	8,330.00	8,330.00
2.	1. Adapter-01 Pc 2. Base-1 Pc	Shoyari Ghat	MODS Zone-2	01 Set	2,830.00	2,830.00
3.	1. Adapter-01 Pc 2. Base-1 Pc	Azimpur Sewer Pump	MODS Zone-2	01 Set	2,830.00	2,830.00
4.	1. Sensor Cabel-1 Pc 2. Base-1 Pc	Nobodoy A Block Water Pump	MODS Zone-3	01 Set	2,940.00	2,940.00
5.	1. Adapter-1 Pc 2. Base-1 Pc	Chanmia Housing Pump	MODS Zone-3	01 Set	2,830.00	2,830.00
6.	1. Sensor Cabel-1 Pc 2. Base-1 Pc	Khilji Road Pump	MODS Zone-3	01 Set	2,940.00	2,940.00
7.	1. Sensor cable-01 Pc 2. Adapter-01 Pc	Section-2/19	MODS Zone-4	01 Set	2242.00	2242.00
Total Amount:						24,942.00
In Word: Twenty-Four Thousand Nine Hundred and Forty-Two Taka Only.						

Note: Total Service Machine 15 Nos Under Pump House Covered 33 Nos.

Terms and Conditions

- Intelligent Technology** will provide (01) one-month service warranty for device; however, no warranty is provided for attendance device & any others spare parts if,

Handwritten Signature: Alex




- Warranty doesn't acceptable against natural disaster, burn case for AC INPUT power fluctuation or any mechanical/Physical damage.
 - Warranty doesn't acceptable of the product if "warranty void seal" removed or tempered.
2. The Device and its accessories cannot be exchanged or replaced once used.
 3. The payment for the services will be made through cash/an account payee cheque/DD/pay order, payable to **Intelligent Technology**, along with a corresponding work order.
 4. This bill must be paid by Bangladesh Taka Only.

Please take necessary step to clear the bill to the following accounts details.

Account Name: Intelligent Technology
Bank Name: Bank Asia Ltd.
Branch: Satmosjid Road
Account Number: 06933000526
Account Type: Current
Receiving Bank Routing Number: 070264034
Mobile: 01904400201

Thank you for your prompt attention to this matter. We assure you that we provide our best service at all times.

Thank you once again.
Yours Sincerely,



Engr. Shamsul Alam
Manager (Technical)
For, **Intelligent Technology**
Cell: +88 01904400202, +88 01904400203.
E-mail: alam.itechbd@gmail.com
info.itechbd@yahoo.com
Web: www.itechbd.com

SERVICE / MAINTENANCE REPORT

For Biometric (Fingerprint / Face Detection) Time Attendance System

Maintenance Card No	: IT-DW-MSA-	Service Date : 19.04.2026
Client Name & Location	: DHAKA WASA, 98, Kazi Nazrul Islam Avenue, Kawran Bazar, Dhaka-1215.	
Office / Zone / Site Name	: MODS ZONE - 02	
Office / Zone / Site Location	: Rahmatullah Gird's school water pump.	
Application System	: Biometric (Fingerprint / Face Detection) Time Attendance System.	

Reported Fault By The Client :	The device was automatic restart problem.
Action Taken By The Engineer/ Technician Comments:	Now the device service complete and the device was connected.
Materials Used:	i) Base - 2 pcs. ii) Adapter - 2 pcs.
Engineer / Technician Name : Biplob Kumar Roy	
Engineer / Technician Signature : Biplob	Date : 19.04.2026
Client Representative's Name : MD. AL-AMIN	
Client Representative's Designation : O. P. O	
Client Representative's Signature : 	
Client Representative's Seal:	
Date: 19.04-2026	
Note:	

SERVICE / MAINTENANCE REPORT

For Biometric (Fingerprint / Face Detection) Time Attendance System

Maintenance Card No : IT-DW-MSA- Service Date : 09.04.2026
 Client Name & Location : DHAKA WASA, 98, Kazi Nazrul Islam Avenue, Kawran Bazar, Dhaka-1215.
 Office / Zone / Site Name : MODS ZONE - 02
 Office / Zone / Site Location : Shoarighat pump
 Application System : Biometric (Fingerprint / Face Detection) Time Attendance System.

Reported Fault By The Client :	The device was automatic restart.
Action Taken By The Engineer/ Technician Comments:	The device service was completed and install.
Materials Used:	i) Base - 2 pcs. ii) Adapter - 2 pcs.
Engineer / Technician Name :	Biplob Kumar Roy
Engineer / Technician Signature :	Biplob
	Date : 09.04.2026
Client Representative's Name :	Sommat Mridha
Client Representative's Designation :	O.P.O.
Client Representative's Signature :	
Client Representative's Seal:	
	Date : 09.04.2026
Note:	



Intelligent

for intelligent solution.

SERVICE / MAINTENANCE REPORT

For Biometric (Fingerprint / Face Detection) Time Attendance System

Maintenance Card No : IT-DW-MSA, Service Date : 09.04.2026
Client Name & Location : DHAKA WASA, 98, Kazi Nazrul Islam Avenue, Kawran Bazar, Dhaka-1215.
Office / Zone / Site Name : MODS ZONE -02
Office / Zone / Site Location : Azimpur sewage pump
Application System : Biometric (Fingerprint / Face Detection) Time Attendance System.

Reported Fault By The Client :	The device was automatic restart.
Action Taken By The Engineer/ Technician Comments:	The device service is was completed and ~~install~~ install.
Materials Used:	i) Base - 1 pes ii) Adapter - 1 pes.
Engineer / Technician Name :	Biplob kumar Roy
Engineer / Technician Signature :	Biplob
	Date : 09.04.2026
Client Representative's Name :	tanvir kumar
Client Representative's Designation :	in ch
Client Representative's Signature :	tanvir
Client Representative's Seal:	
	Date: 09.04.2026
Note:	

187(Gnd Floor), Green Road, Dhanmondi Dhaka-1205, Bangladesh. Cell: +88 01904400202, +88 01904400203

E-mail: info@itechbd@yahoo.com Web: www.itechbd.net

09/04/26
Sardar Jaechur Hossain
Assistant Engineer
MODS Zone-2, Dhaka WASA



Intelligent

for intelligent solution

SERVICE / MAINTENANCE REPORT

For Biometric (Fingerprint / Face Detection) Time Attendance System


Maintenance Card No : IT-DW-MSA- Service Date : 08.04.2026

Client Name & Location : DHAKA WASA, 98, Kazi Nazrul Islam Avenue, Kawran Bazar, Dhaka-1215.

Office / Zone / Site Name : Noboday A block water pump

Office / Zone / Site Location : MODS Zone-03



Application System : Biometric (Fingerprint / Face Detection) Time Attendance System.

Reported Fault By The Client :	The device was automatic resistant and base broken.		
Action Taken By The Engineer/ Technician Comments:	The device service is completed and installed completed.		
Materials Used:	① Base - 1 pc ② Adapter - 1 pc		
Engineer / Technician Name :	Md, Rosel Hossain		
Engineer / Technician Signature :			Date : 08.04.2026
Client Representative's Name :	 মোঃ জিয়া উদ্দিন উপ-সহকারী প্রকৌশলী এডম জোন-৩ নাকা ওয়াস		
Client Representative's Designation :			
Client Representative's Signature :			
Client Representative's Seal:			Date:
Note:			

SERVICE / MAINTENANCE REPORT

For Biometric (Fingerprint / Face Detection) Time Attendance System

Maintenance Card No	: IT-DW-MSA-	Service Date : 08.04.2026
Client Name & Location	: DHAKA WASA, 98, Kazi Nazrul Islam Avenue, Kawran Bazar, Dhaka-1215.	
Office / Zone / Site Name	: Channia Housing Water pump	
Office / Zone / Site Location	: Mads zone-03	
Application System	: Biometric (Fingerprint / Face Detection) Time Attendance System.	

Reported Fault By The Client :	The device was automatic restarts problem.
Action Taken By The Engineer/ Technician Comments:	Now service complet and device reinstalled in pump house.
Materials Used:	① Base - 1 pc ② Adaption - 1 pc ③ Internet cable
Engineer / Technician Name :	Md. Rasel Hossain
Engineer / Technician Signature :	 Date : 08.04.2026
Client Representative's Name :	
Client Representative's Designation :	
Client Representative's Signature :	
Client Representative's Seal:	 মোঃ জিয়া উদ্দিন উপ-সহকারী প্রকৌশলী মডস জোন-৩ ঢাকা ওয়াশা Date:
Note:	

SERVICE / MAINTENANCE REPORT

For Biometric (Fingerprint / Face Detection) Time Attendance System



Maintenance Card No : IT-DW-MSA- Service Date : 08.09.2026

Client Name & Location : DHAKA WASA, 98, Kazi Nazrul Islam Avenue, Kawran Bazar, Dhaka-1215.

Office / Zone / Site Name : khilji Road water Pump

Office / Zone / Site Location : Mod3 Zone -03

Application System : Biometric (Fingerprint / Face Detection) Time Attendance System.

Reported Fault By The Client :	The device was restart problem and base broken.
Action Taken By The Engineer/ Technician Comments:	The device is service complet and reinstalled.
Materials Used:	① Base - 1 pc ② Adapter - 1 pc
Engineer / Technician Name : Md. Rosel Hossain	
Engineer / Technician Signature : 	Date : 08.09.2026
Client Representative's Name :	
Client Representative's Designation :	
Client Representative's Signature :	
Client Representative's Seal:	Date:
 মোঃ জিয়া উদ্দিন উপ-সহকারী প্রকৌশলী ওডস জান-৩, ঢাকা ওয়াস	
Note:	

SERVICE / MAINTENANCE REPORT

For Biometric (Fingerprint / Face Detection) Time Attendance System

Maintenance Card No : IT-DW-MSA- Service Date : 07.04.2026

Client Name & Location : DHAKA WASA, 98, Kazi Nazrul Islam Avenue, Kawran Bazar, Dhaka-1215.

Office / Zone / Site Name : MODS ZONE - 04

Office / Zone / Site Location : Dhaka wasa 2/19 water pump.

Application System : Biometric (Fingerprint / Face Detection) Time Attendance System.

Reported Fault By The Client :	The device was automatic restart problem.	
Action Taken By The Engineer/ Technician Comments:	Now the device service complete and the device was connected.	
Materials Used:	i) Sencor cable, A ii) Adapter - 1 pcs. iii) Base - 2 pcs.	
Engineer / Technician Name :	Biplob Kumar Roy	
Engineer / Technician Signature :	Junioun Engineer	Date : 07.04.2026
Client Representative's Name :	মোঃ আব্দুল জাকারিয়া	
Client Representative's Designation :	মি. ডি	
Client Representative's Signature :	জাকারিয়া	
Client Representative's Seal:		Date : 07.04.26
Note:		